




Site Location Plan



View 1 - Section 1 Elevation



View 2 - Section 1 Elevation




Site Layout Plan



View 5 - Crack in Section 3

Approx 1.7m long full height vertical crack towards west end of Section 3 to be re-pointed

Mortar haunch coping to be added to be added to full length of Section 2



View 3 - Section 2 Elevation

Top 2-3 courses to be deconstructed and rebuilt for full length of Section 2

Area of loose, displaced masonry at east end of Section 2 - Line of loose stones at edge of discontinuity to be rebedded, stitching discontinuity in wall

Re-point full height of wall for full length of Section 2



View 4 - Local Damage in Section 3

Area of failure at joint between two constructions in Section 3 - locally de-construct and rebuild top 2-3 courses, stitching two sections together

Re-point areas of mortar loss, failure and through joint cracking locally