

APPENDIX A - PHOTOGRAPHS




COMMUNAL STAIRCASE (Survey – 21/07/2017)



Pic.1 Internal wall cracks




Pic.2 Internal wall crack



Pic.3 Internal wall crack



Pic.4- Internal wall crack



Pic 5 – Internal wall crack




Pic. 6 Hairline crack




Pic 7 Internal wall crack



Pic8 Internal wall crack



Pic9 Internal wall crack




Pic10 Internal wall crack



Pic11 Internal wall crack




Pic12 Internal wall crack



Pic13 Internal wall crack



Pic14 Internal wall crack



Pic15 Internal wall crack



Pic16 Internal wall crack



Pic17 Internal wall crack



Pic18 Internal wall crack



Pic19 Internal wall crack



Pic20 Internal wall crack

NORTH EAST ELEVATION
(Survey – 21/07/2017)



Pic.21 – Stained brickwork



Pic.22 – Stained brickwork



Pic.23 – Stained brickwork




Pic.24 – Spalled concrete



Pic 25 - Facing brick



Pic. 26- spalled concrete/staining



Pic 27-spalled concrete



Pic 28- Stained brickwork



Pic 29 Stained brickwork

P30

SOUTH EAST ELEVATION (Survey – 21/07/2017)



Pic.31 – Cracks in RC Column



Pic.32 – Cracking in RC Column



Pic.33 – Defective pointing in brickwork



Pic.34 – Spalled concrete edge

NORTH WEST ELEVATION (Survey – 08/08/2017)



Pic. 35 – Brick facade



Pic. 36 Spalled slab edge concrete



Pic. 37 – Spalled concrete



Pic. 38 – Opening in facing brick