

Manhole Data						Sheet: 1 of 11	
Site: Paignton Community College, ONS1172(revA)						Date: July 2018	
Manhole Number	Cover Level	Diagram		Pipe Diameter	Depth (m)	Invert (m)	Comments
F1	54.19		A B C D E F X	100 VC	0.84	53.35	
F2	54.11		A B C D E F X	100 VC 100 VC	1.00 0.90	53.11 53.21	
F3	54.16		A B C D E F X	100 VC	1.22	52.94	
F4	54.20		A B C D E F G X	100 VC 100 VC	1.42 1.34	52.78 52.86	X:- silted
F5	54.15		A B C D E F X	100 VC 100 VC	1.59 1.59	52.56 52.56	

Pipe Materials: VC=vitrified clay PC=precast concrete CI=cast iron DI=ductile iron PVC=plastic PF=pitch fibre BRK=brick ST=stone AC=asbestos cement UK=unknown G=gully RW=roof water

Onspot Surveys Ltd

5 Henty Avenue . Dawlish . Devon . EX7 0AW Tel: 07778 120 981 . 01626 865397
info@onspot.co.uk . www.onspot.co.uk

Manhole Data

Sheet: 2 of 11

Site: Paignton Community College, ONS1172(revA)

Date: July 2018

Manhole Number	Cover Level	Diagram		Pipe Diameter	Depth (m)	Invert (m)	Comments
F6	52.22		A B C D E F X	100 VC 100 VC 150 VC 100 VC	 0.66 0.59 0.66	 51.56 51.63 51.56	
F7	50.63		A B C D E F G X	100 VC 100 VC 100 VC 100 VC 100 VC 100 VC 150 VC 150 VC	 0.77 0.77	 49.86 49.86	H:- 150VC Depth 0.66m IL 49.97m G:- changes to 100Ø just upstream
F8	50.25		A B C D E F X	150 VC 150 VC 100 VC 150 VC	0.73 0.73 0.73	49.52 49.52 49.52	
F9	48.47		A B C D E F G X	150 VC 150 VC	1.93 1.93	46.54 46.54	X:- interceptor 100Ø rodeye No easy chamber access
F10	54.13		A B C D E F X	150 VC 100 VC 100 VC 100 VC	0.64 0.64	53.49 53.49	

Pipe Materials: VC=vitrified clay PC=precast concrete CI=cast iron DI=ductile iron PVC=plastic PF=pitch fibre BRK=brick ST=stone AC=asbestos cement UK=unknown G=gully RW=roof water

Onspot Surveys Ltd

5 Henty Avenue . Dawlish . Devon . EX7 0AW Tel: 07778 120 981 . 01626 865397
info@onspot.co.uk . www.onspot.co.uk

Manhole Data						Sheet: 3 of 11	
Site: Paignton Community College, ONS1172(revA)						Date: July 2018	
Manhole Number	Cover Level	Diagram		Pipe Diameter	Depth (m)	Invert (m)	Comments
F11	53.23		A B C D E F X	100 VC 100 VC 100 VC	0.46 0.54 0.54	52.77 52.69 52.69	
F12	51.96		A B C D E F X	100 PVC 100 VC 100 VC 100 VC 100 VC 100 VC	0.49 0.56 0.53 0.53 0.41	51.53 51.46 51.46	
F13	51.81		A B C D E F X	100 PVC 100 PVC 100 PVC	0.57 0.57 0.63	51.24 51.24 51.18	
F14	51.47		A B C D E F G X	100 VC 150 VC 100 VC	1.08 0.98	50.39 50.49	
F15	51.20		A B C D E F X	150 VC 100 VC 100 VC 100 VC	0.97	50.23	

Pipe Materials: VC=vitrified clay PC=precast concrete CI=cast iron DI=ductile iron PVC=plastic PF=pitch fibre BRK=brick ST=stone AC=asbestos cement UK=unknown G=gully RW=roof water

Onspot Surveys Ltd

5 Henty Avenue . Dawlish . Devon . EX7 0AW Tel: 07778 120 981 . 01626 865397
info@onspot.co.uk . www.onspot.co.uk

Manhole Data

Site: Paignton Community College, ONS1172(revA)

Date: July 2018






Manhole Number	Cover Level	Diagram		Pipe Diameter	Depth (m)	Invert (m)	Comments
F16	50.79		A	150 VC	0.81	49.98	B:- lined
			B C D E F	X	100 PVC	0.71	
F17	50.56		A	150 VC	0.88	49.68	
			B	100 VC	0.57	49.99	
			C	100 VC	0.76	49.80	
			D	100 VC	0.76	49.80	
			E F	X	150 VC	0.88	
F18	54.34		A	100 PVC	0.97	53.37	
			B C D E F	X	100 PVC	0.97	
F19	54.20		A	100 VC	0.96	53.24	
			B C	100 VC			
			D E F G X	100 VC	0.96	53.24	
F20	54.02		A	100 VC	1.11	52.91	
			B C D E F	100 VC	1.17	52.85	
			X	100 VC	1.17	52.85	

Pipe Materials: VC=vitrified clay PC=precast concrete CI=cast iron DI=ductile iron PVC=plastic PF=pitch fibre BRK=brick ST=stone AC=asbestos cement UK=unknown G=gully RW=roof water

Onspot Surveys Ltd

5 Henty Avenue . Dawlish . Devon . EX7 0AW Tel: 07778 120 981 . 01626 865397

info@onspot.co.uk . www.onspot.co.uk

Manhole Data						Sheet: 5 of 11	
Site: Paignton Community College, ONS1172(revA)						Date: July 2018	
Manhole Number	Cover Level	Diagram		Pipe Diameter	Depth (m)	Invert (m)	Comments
F21	53.67		A	100 VC	1.10	52.57	A:- backdrop
			B C D E F				
F22	53.13		A	100 VC	1.30	51.83	
			B C D E F	X	100 VC	1.30	
F23	53.09		A B C D E F	100 VC 100 VC 100 VC 100 VC 100 VC	0.75	52.34	
X	100 VC						
F24	52.59		A	100 VC	0.93	51.66	
			B C D E F G X	150 VC	0.93	51.66	
F25	55.33		A	150 VC	1.68	53.65	A:- backdrop
			B C D E F	150 VC			
X	150 VC	1.68	53.65				

Pipe Materials: VC=vitrified clay PC=precast concrete CI=cast iron DI=ductile iron PVC=plastic PF=pitch fibre BRK=brick ST=stone AC=asbestos cement UK=unknown G=gully RW=roof water

Onspot Surveys Ltd

5 Henty Avenue . Dawlish . Devon . EX7 0AW Tel: 07778 120 981 . 01626 865397
info@onspot.co.uk . www.onspot.co.uk

Manhole Data						Sheet: 6 of 11	
Site: Paignton Community College, ONS1172(revA)						Date: July 2018	
Manhole Number	Cover Level	Diagram		Pipe Diameter	Depth (m)	Invert (m)	Comments
F26	55.17		A	100 VC	0.81	54.36	Part soil filled
			B	100 VC			
F27	52.37		A	100 PVC	0.91	51.46	
			B	100 PVC	0.96	51.41	
F28	53.66		A	150 PVC			
			B	100 VC			
F29		In building Not lifted From F5 To F6	C	100 VC			
			D	100 VC			
F30	54.27	Inlay cover Not lifted To F5	E				
			F				
			X				

Pipe Materials: VC=vitrified clay PC=precast concrete CI=cast iron DI=ductile iron PVC=plastic PF=pitch fibre BRK=brick ST=stone AC=asbestos cement UK=unknown G=gully RW=roof water

Onspot Surveys Ltd

5 Henty Avenue . Dawlish . Devon . EX7 0AW Tel: 07778 120 981 . 01626 865397
info@onspot.co.uk . www.onspot.co.uk

Manhole Data

Sheet: 7 of 11

Site: Paignton Community College, ONS1172(revA)

Date: July 2018

Manhole Number	Cover Level	Diagram		Pipe Diameter	Depth (m)	Invert (m)	Comments
S1	55.29		A	150 PVC	1.79	53.50	
			B C D E F	X	150 PVC	1.79	
S2	54.21		A	150 PVC	0.82	53.39	Silt in inverts
			B	150 PVC	0.82	53.39	
C	150 PVC	0.82	53.39				
D E F	X	150 PVC	0.82	53.39			
S3	54.06		A	100 VC	0.75	53.31	
			B C D E F	X			
S4	53.70		A	100 VC	0.61	53.09	
			B C D E F G	X			
S5	53.56		A	150 VC	0.67	52.89	A:- backdrop
			B C D E F	X			

Pipe Materials: VC=vitrified clay PC=precast concrete CI=cast iron DI=ductile iron PVC=plastic PF=pitch fibre BRK=brick ST=stone AC=asbestos cement UK=unknown G=gully RW=roof water

Onspot Surveys Ltd

5 Henty Avenue . Dawlish . Devon . EX7 0AW Tel: 07778 120 981 . 01626 865397

info@onspot.co.uk . www.onspot.co.uk

Manhole Data						Sheet: 8 of 11	
Site: Paignton Community College, ONS1172(revA)						Date: July 2018	
Manhole Number	Cover Level	Diagram		Pipe Diameter	Depth (m)	Invert (m)	Comments
S6	53.09		A B C D E F X	150 VC 100 VC 100 VC 150 VC	1.30 1.30	51.79 51.79	Rodeye above interceptor at X
S7	51.11		A B C D E F X	150 VC 150 VC	0.77 0.77	50.34 50.34	X:- interceptor
S8	50.01		A B C D E F X	150 PVC 150 PVC	0.85 0.85	49.16 49.16	
S9	55.43		A B C D E F G X	150 VC 150 VC	1.40 1.40	54.03 54.03	X:- interceptor
S10	55.38		A B C D E F X	150 VC 100 VC 100 VC 150 VC	0.95 0.95	54.43 54.43	X:- interceptor

Pipe Materials: VC=vitrified clay PC=precast concrete CI=cast iron DI=ductile iron PVC=plastic PF=pitch fibre BRK=brick ST=stone AC=asbestos cement UK=unknown G=gully RW=roof water

Onspot Surveys Ltd

5 Henty Avenue . Dawlish . Devon . EX7 0AW Tel: 07778 120 981 . 01626 865397
info@onspot.co.uk . www.onspot.co.uk

Manhole Data						Sheet: 9 of 11	
Site: Paignton Community College, ONS1172(revA)						Date: July 2018	
Manhole Number	Cover Level	Diagram		Pipe Diameter	Depth (m)	Invert (m)	Comments
S11	54.91		A B C D E	100 PVC	0.60	54.31	
			X	100 PVC	0.63	54.28	
S12	54.52		A B C D E	100 PVC 100 PVC	0.48 0.51	54.04 54.01	
			X	100 PVC	0.51	54.01	
S13	53.97		A B C D E	100 PVC 100 PVC	0.33 0.36	53.64 53.61	
			X	100 PVC	0.36	53.61	
S14	53.76		A B C D E	100 PVC 100 PVC	0.51 0.46	53.25 53.30	
			X	100 PVC	0.51	53.25	
S15	52.20		A B C D E	100 PVC	0.33	51.87	
			X	100 PVC	0.33	51.87	
S16		Buried From S6 To S7					

Pipe Materials: VC=vitrified clay PC=precast concrete CI=cast iron DI=ductile iron PVC=plastic PF=pitch fibre BRK=brick ST=stone AC=asbestos cement UK=unknown G=gully RW=roof water

Onspot Surveys Ltd

5 Henty Avenue . Dawlish . Devon . EX7 0AW Tel: 07778 120 981 . 01626 865397
info@onspot.co.uk . www.onspot.co.uk

Manhole Data

Site: Paignton Community College, ONS1172(revA)

Date: December 2023

Manhole Number	Cover Level	Diagram		Pipe Diameter	Depth (m)	Invert (m)	Comments
F50	54.58		A	150 PVC	1.15	53.43	
			B				
F51	54.09		A	100 PVC	0.87	53.22	
			B	150 PVC	0.90	53.19	
F53	53.31		A	100 PVC	0.68	52.63	
			B	150 PVC	0.72	52.59	
F54	53.67		A	100 PVC	1.00	52.67	
			B	100 VC	0.95	52.72	
F55	53.67		A	100 PVC	1.00	52.67	
			B	100 PVC	0.93	52.74	
			C	100 PVC	0.93	52.74	
			D				
			E				
			F				
			X	100 PVC	1.00	52.67	

Pipe Materials: VC=vitrified clay PC=precast concrete CI=cast iron DI=ductile iron PVC=plastic PF=pitch fibre BRK=brick ST=stone AC=asbestos cement UK=unknown G=gully RW=roof water

Onspot Surveys Ltd

5 Henty Avenue . Dawlish . Devon . EX7 0AW Tel: 07778 120 981 . 01626 865397

info@onspot.co.uk . www.onspot.co.uk

Manhole Data

Site: Paignton Community College, ONS1172(revA)

Date: December 2023

Manhole Number	Cover Level	Diagram		Pipe Diameter	Depth (m)	Invert (m)	Comments
F56	53.44		A	100 PVC	1.17	52.27	
			B	100 PVC	1.23	52.21	
F57	52.97		A	100 PVC	1.32	51.65	
			B	100 PVC	1.37	51.60	
F58	52.71		A	100 PVC	1.12	51.59	
			B	100 PVC	1.17	51.54	
S50	53.68		A	150 PVC	0.70	52.98	
			B	100 PVC	0.63	53.05	
S51	53.63		A	150 PVC	1.36	52.27	
			B	150 PVC	0.70	52.98	
S51	53.63		A	150 PVC	1.36	52.27	
			B	150 PVC	1.36	52.27	

Pipe Materials: VC=vitrified clay PC=precast concrete CI=cast iron DI=ductile iron PVC=plastic PF=pitch fibre BRK=brick ST=stone AC=asbestos cement UK=unknown G=gully RW=roof water

Onspot Surveys Ltd

5 Henty Avenue . Dawlish . Devon . EX7 0AW Tel: 07778 120 981 . 01626 865397

info@onspot.co.uk . www.onspot.co.uk