External Repairs to Lydiard House

Former Stable Block Photographs



Elevation 9



Elevation 10

There is no photograph of Elevation 11 as this the only work required is to be carried out to the guttering



Elevation 12



Elevation 13



Elevation 14