

<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>  <b><u>SCHEDULE OF WORKS</u></b>  <b><u>UPPER UPPER GROUND FLOOR LEVEL</u></b>  <b><u>DOOR G1 (Stair Circulation 13)</u></b>					
A	Carefully strip out existing door, door frame and achitraves and dispose from site. Retain signage and fingerguard and set aside for re-use. Make good disturbed surfaces.	Item			
B	Supply and fix a new FD30 certified door set comprising new 44mm thick paint finish door (& softwood door and fanlight frame) to meet the requirements of the BM Trada scheme for Fire Doors and Doorsets (to BS 476 part 22 or BS EN 1634-1). Include combined smoke seals and intumescent strip set in the frame, hardwood lipped, pair and half FD30 rated hinges, 2nr SAA kick plates, 1nr SAA pull handle, 1nr SAA push plate, 2nr clear FD30 toughened vision panels (and fanlight) using fire & heat resistant glazing (Kitemarked) using an intumescent glazing / bedding system, supply and fix 1nr FD30 Briton door close (2003V with silver arm / cover. (Doorsets: Leaderflush Shapland / Premdor or similar approved and certified by BWF-Certifire or BM Trada Q-Mark). Supply and fix new fire resistant lever handles, Union mortice lock with 'suited' key to match the existing.	Item			
C	Supply and mechanically fix new softwood architraves to match the existing in all respects.	Item			
	<b><u>Decorations</u></b>				
D	Prepare and decorate the new door, door frame and architraves with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC.	Item			
	<b><u>Miscellaneous</u></b>				
E	Refix previously set aside fingerguard and 'Fire Door Keep Shut' signage.	Item			
2004170		TO COLLECTION	£		
3/1					

<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>					
<b><u>SCHEDULE OF WORKS</u></b>					
<b><u>DOOR G2 (Circulation 1)</u></b>					
A	Carefully strip out existing door, door frame and achitraves and dispose from site. Retain signage and fingerguards. Make good disturbed surfaces.	Item			
B	Supply and fix a new FD30 certified door set comprising new 44mm thick paint finish door (& softwood door frame) to meet the requirements of the BM Trada scheme for Fire Doors and Doorsets (to BS 476 part 22 or BS EN 1634-1). Include combined smoke seals and intumescent strip set in the frame, hardwood lipped, pair and half FD30 rated hinges, 2nr SAA kick plates, 1nr SAA pull handle, 1nr SAA push plate, 2nr FD30 vision panels using clear fire & heat resistant toughened glazing (Kitemarked) using an intumescent glazing / bedding system, supply and fix 1nr FD30 Briton door close (2003V with silver arm / cover. (Doorsets: Leaderflush Shapland / Premdor or similar approved and certified by BWF-Certifire or BM Trada Q-Mark).	Item			
C	Include for supplying and fixing new softwood pencil round architrave to match the existing in all respects to each side of the new door frame.	Item			
<b><u>Decorations</u></b>					
D	Prepare and decorate the new door, door frame and architraves with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instructions. Dulux Paints, Colour TBC.	Item			
<b><u>Miscellaneous</u></b>					
E	Refix previously set aside fingerguard and door signage.	Item			
2004170		TO COLLECTION		£	
3/2					

<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>					
<b><u>SCHEDULE OF WORKS</u></b>					
<b><u>DOOR G3 (Resources 6)</u></b>					
A	Carefully strip out existing door, door frame and achitraves and dispose from site. Retain signage and fingerguard and set aside for re-use. Make good disturbed surfaces.	Item			
B	Supply and fix a new FD30 certified door set comprising new 44mm thick paint finish door (& softwood door frame) to meet the requirements of the BM Trada scheme for Fire Doors and Doorsets (to BS 476 part 22 or BS EN 1634-1). Include combined smoke seals and intumescent strip set in the frame, hardwood lipped, pair and half FD30 rated hinges, 2nr SAA kick plates, SAA pull handle, SAA push plate, 2nr clear FD30 vision panels using fire & heat resistant toughened glazing (Kitemarked) using an intumescent glazing / bedding system, supply and fix 1nr FD30 Briton door closer (2003V with silver arm / cover). (Doorsets: Leaderflush Shapland / Premdor or similar approved and certified by BWF-Certifire or BM Trada Q-Mark). Supply and fix new fire resistant lever handles, Union mortice lock with 'suited' key to match the existing.	Item			
C	Supply and mechanically fix new softwood arcitraves to match the existing in all respects.	Item			
<b><u>Decorations</u></b>					
D	Prepare and decorate the new door, door frame and architraves with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC.	Item			
<b><u>Miscellaneous</u></b>					
E	Refix previously set aside fingerguard and 2nr 'Fire Door Keep Shut' signs.	Item			
2004170		TO COLLECTION	£		
3/3					

## FIRE SAFETY UPGRADE

### STANSFIELD HALL PRIMARY SCHOOL

## SCHEDULE OF WORKS

**DOOR G4 (Mezzanine Sensory Room 51)**

- |   |  |      |
|---|--|------|
| A | Supply and fix 1nr FD 30 Briton door closer (2003V with silver arm / cover).   | Item |
| B | Supply and fix 2nr 76mm aluminium circular 'Fire Door Keep Shut' signs. Screwfix, <a href="http://www.screwfix.com">www.screwfix.com</a>   | Item |
| C | Carefully remove the fingerguard, strip out the existing hinges dispose. Supply and fix 3nr FD30 fire rated hinges. Reinstall fingerguard. | Item |

2004170

TO COLLECTION £

# **FIRE SAFETY UPGRADE** **STANSFIELD HALL PRIMARY SCHOOL**

## SCHEDULE OF WORKS

**DOOR G5 (Circulation 38)**

A	No work required (2021 Project)
---	---------------------------------

2004170

3/5

TO COLLECTION £

£

<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>  <b><u>SCHEDULE OF WORKS</u></b>  <b><u>DOOR G6 (Business Manager's Office 25)</u></b>					
A	Carefully strip out existing door, door frame and achitraves and dispose from site. Retain signage, fingerguard and digital lock and set aside for re-use. Make good disturbed surfaces.				
B	Supply and fix a new FD30 certified door set comprising new 44mm thick paint finish door (& softwood door frame) to meet the requirements of the BM Trada scheme for Fire Doors and Doorsets (to BS 476 part 22 or BS EN 1634-1). Include combined smoke seals and intumescent strip set in the frame, hardwood lipped, pair and half FD30 rated hinges, 2nr SAA kick plates, 2nr clear FD30 vision panels using fire & heat resistant toughened glazing (Kitemarked) using an intumescent glazing / bedding system, supply and fix 1nr FD30 Briton door closer (2003V with silver arm / cover). (Doorsets: Leaderflush Shapland / Premdor or similar approved and certified by BWF-Certifire or BM Trada Q-Mark). Supply and fix new fire resistant lever handles, Union mortice lock with 'suited' key to match the existing.				
C	Supply and mechanically fix new softwood arcitraves to match the existing in all respects.	Item			
<b><u>Decorations</u></b>					
D	Prepare and decorate the new door, door frame and architraves with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC.	Item			
<b><u>Miscellaneous</u></b>					
E	Refix previously set aside fingerguard and door signage. Hand back the digital lock to the school.	Item			
2004170		TO COLLECTION		£	
3/6					

<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>					
<b><u>SCHEDULE OF WORKS</u></b>					
<b><u>DOOR G7 (Reception Office 11)</u></b>					
A	Carefully strip out existing door, door frame and achitraves and dispose from site. Retain signage and fingerguard and set aside for re-use. Make good disturbed surfaces.	Item			
B	Supply and fix a new FD30 certified door set comprising new 44mm thick paint finish door (& softwood door frame) to meet the requirements of the BM Trada scheme for Fire Doors and Doorsets (to BS 476 part 22 or BS EN 1634-1). Include combined smoke seals and intumescent strip set in the frame, hardwood lipped, pair and half FD30 rated hinges, 2nr SAA kick plates, 2nr clear FD30 vision panels using fire & heat resistant toughened glazing (Kitemarked) using an intumescent glazing / bedding system, supply and fix 1nr FD30 Briton door closer (2003V with silver arm / cover). (Doorsets: Leaderflush Shapland / Premdor or similar approved and certified by BWF-Certifire or BM Trada Q-Mark). Supply and fix new fire resisitant lever handles, Union mortice lock with 'suited' key to match the existing.	Item			
C	Supply and mechanically fix new softwood arcitraves to match the existing in all respects.	Item			
<b><u>Decorations</u></b>					
D	Prepare and decorate the new door, door frame and architraves with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC.	Item			
<b><u>Miscellaneous</u></b>					
E	Refix previously set aside fingerguard and door signage.	Item			
2004170		TO COLLECTION		£	
3/7					

<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>  <b><u>SCHEDULE OF WORKS</u></b>  <b><u>DOOR G8 (Reception Office11)</u></b>					
A	Carefully strip out existing double serving hatch doors and dispose from site. Retain glazing for re-use. Frame and architraves to remain in place.	Item			
B	Supply and fix 2nr softwood hatch doors, refix pyro glass and install using intumescent bedding. Include for combined smoke seals and intumescent strip set in the doors, 4nr FD30 hinges, 4nr 76mm aluminium circular 'Fire Door Keep Shut' signs, 4nr fire resitant chrome finish steel bolts. Screwfix, <a href="http://www.screwfix.com">www.screwfix.com</a>	Item			
<b><u>Decorations</u></b>					
C	Prepare and decorate the new doors with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC.	Item			
D	Prepare and decorate the previously painted door frame and architraves with 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC.	Item			
2004170		TO COLLECTION	£		
3/8					



A	<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>  <b><u>SCHEDULE OF WORKS</u></b>  <b><u>DOOR G9 (Circulation 16)</u></b> No work required (2021 Project)				
	2004170	TO COLLECTION	£		

<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>					
<b><u>SCHEDULE OF WORKS</u></b>					
<b><u>DOOR G10 (Teaching 18)</u></b>					
A	Carefully strip out existing door, door frame and achitraves and dispose from site. Retain signage and fingerguards. Make good disturbed surfaces.	Item			
B	Supply and fix a new FD30 certified door set comprising new 44mm thick paint finish door (& softwood door frame) to meet the requirements of the BM Trada scheme for Fire Doors and Doorsets (to BS 476 part 22 or BS EN 1634-1). Include combined smoke seals and intumescent strip set in the frame, hardwood lipped, pair and half FD30 rated hinges, 2nr SAA kick plates, 2nr FD30 vision panels using clear fire & heat resistant toughened glazing (Kitemarked) using an intumescent glazing / bedding system, supply and fix 1nr FD30 Briton door close (2003V with silver arm / cover, 2nr 76mm diameter screw fixed 'Fire Door Keep Shut' signs. (Doorsets: Leaderflush Shapland / Premdor or similar approved and certified by BWF-Certifire or BM Trada Q-Mark).Supply and fix new fire rated lever handles, Union mortice lock with escutcheon and 'suited' key to match the existing.	Item			
C	Include for supplying and fixing new softwood pencil round architrave to match the existing in all respects to each side of the new door frame.	Item			
<b><u>Decorations</u></b>					
D	Prepare and decorate the new door, door frame and architraves with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC.	Item			
<b><u>Miscellaneous</u></b>					
E	Refix previously set aside fingerguard and door signage.	Item			
2004170		TO COLLECTION	£		
3/10					

<b><u>FIRE SAFETY UPGRADE</u></b>					
<b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>					
<b><u>SCHEDULE OF WORKS</u></b>					
<b><u>DOOR G11 (Store 19)</u></b>					
A	Carefully strip out existing door, door frame and achitraves and dispose from site. Retain signage and fingerguards. Make good disturbed surfaces.	Item			
B	Supply and fix a new FD30 certified door set comprising new 44mm thick paint finish door (& softwood door frame) to meet the requirements of the BM Trada scheme for Fire Doors and Doorsets (to BS 476 part 22 or BS EN 1634-1). Include combined smoke seals and intumescent strip set in the frame, hardwood lipped, pair and half FD30 rated hinges, 2nr SAA kick plates, 1nr SAA pull handle, 1nr SAA push plate, supply and fix 1nr FD30 Briton door close (2003V with silver arm / cover, 1nr screw fixed 76mm diameter 'Fire Door Keep Shut' signs. (Doorsets: Leaderflush Shapland / Premdor or similar approved and certified by BWF-Certifire or BM Trada Q-Mark). Supply and fix new fire rated lever handles, Union mortice lock with escutcheon and 'suited' key to match the existing.	Item			
C	Include for supplying and fixing new softwood pencil round architrave to match the existing in all respects to each side of the new door frame.	Item			
<b><u>Joinery</u></b>					
D	Within the Store Room only supply and mechanically fix softwood timber battens around the inside of the roof light and add 50mm x 100mm C16 softwood timber joists (to create a ceiling to the lightwell in the store roomonly). Overboard with 12.5mm Gypsum fireboard. Tape joints and apply 3mm Gypsum plaster skim. Include for temporarily relocating any storage and electrical services / lighting. Reinstate on completion of the work. remaining part roof light in the lobby is to remain as existing.	Item			
<b><u>Decorations</u></b>					
E	Prepare and decorate the new door, door frame and architraves with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC.	Item			
F	Prepare and decorate the new plasterboard in store room and lobby with 3nr coats matt emulsion. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour: To match existing.	Item			
2004170		TO COLLECTION		£	
3/11					

## FIRE SAFETY UPGRADE

### STANSFIELD HALL PRIMARY SCHOOL

## SCHEDULE OF WORKS

### Decorations (Cont)

A	Prepare and decorate the previously painted plasterboard ceiling withing the store room with 2nr coats matt emulsion. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour: To match existing.
---	--

Item

### Miscellaneous

B || Refix previously set aside fingerguard and door signage.

Item

2004170

3/12

TO COLLECTION £

<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>					
<b><u>SCHEDULE OF WORKS</u></b>					
<b><u>Door G12 (Lobby 103)</u></b>					
A	Carefully strip out existing door, door frame and achitraves and dispose from site. Retain signage and fingerguards. Make good disturbed surfaces.	Item			
B	Supply and fix a new FD30 certified door set comprising new 44mm thick paint finish door (& softwood door frame) to meet the requirements of the BM Trada scheme for Fire Doors and Doorsets (to BS 476 part 22 or BS EN 1634-1). Include combined smoke seals and intumescent strip set in the frame, hardwood lipped, pair and half FD30 rated hinges, 2nr SAA kick plates, 2nr FD30 vision panels using clear fire & heat resistant toughened glazing (Kitemarked) using an intumescent glazing / bedding system, supply and fix 1nr FD30 Briton door close (2003V with silver arm / cover, 2nr screw 76mm diameter screw fixed 'Fire Door Keep Shut' signs. (Doorsets: Leaderflush Shapland / Premdor or similar approved and certified by BWF-Certifire or BM Trada Q-Mark). Supply and fix new fire rated lever handles and Union mortice lock with escutcheons and 'suited' key to match the existing.	Item			
C	Include for supplying and fixing new softwood pencil round architrave to match the existing in all respects to each side of the new door frame.	Item			
<b><u>Decorations</u></b>					
D	Prepare and decorate the new door, door frame and architraves with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC.	Item			
<b><u>Miscellaneous</u></b>					
E	Refix previously set aside fingerguard and door signage.	Item			
2004170		TO COLLECTION		£	
3/13					

<b><u>FIRE SAFETY UPGRADE</u></b>				
<b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>				
<b><u>SCHEDULE OF WORKS</u></b>				
<b><u>Door G13 (Lobby 103)</u></b>				
A	Carefully remove the fingerguard, strip out the existing hinges dispose. Supply and fix 3nr FD30 fire rated hinges. Reinstate fingerguard. Adjust door to even out gap on hinged edge and leading edge to leave 3mm gaps only. If packing out hinge use intumescent pads. Ensure fingerguard is refixed on completion of the works.	Item		
		</		

A	<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>	Item			
	<b><u>SCHEDULE OF WORKS</u></b>  <b><u>DOOR G14 (Mezzanine Library)</u></b> Lift door to reduce gap at head to 3mm.				
2004170		TO COLLECTION	£		
3/15					

# **FIRE SAFETY UPGRADE** **STANSFIELD HALL PRIMARY SCHOOL**

## SCHEDULE OF WORKS

**DOOR G15 (Resources 58)**

A	No work required (2021 Project)
---	---------------------------------

2004170

3/16

TO COLLECTION £

£



A	<u>FIRE SAFETY UPGRADE</u>							
	<u>STANSFIELD HALL PRIMARY SCHOOL</u>							
	<u>SCHEDULE OF WORKS</u>							
	<u>DOOR G16 (Teaching 17)</u>							
	No work required (2021 Project)							

A	<u>FIRE SAFETY UPGRADE</u>							
	<u>STANSFIELD HALL PRIMARY SCHOOL</u>							
	<u>SCHEDULE OF WORKS</u>							
	<u>DOOR G17 (Teaching 20)</u>							
	No work required (2021 Project)							
							</	

<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>  <b><u>SCHEDULE OF WORKS</u></b>  <b><u>DOOR G18 (Hall Storage 22)</u></b>					
A	Carefully strip out existing double doors, door and combination frame and achitraves and dispose from site.	Item			
B	Supply and fix a new FD30 certified double door set comprising new 44mm thick paint finish door with rebate (& softwood door and side frames) to meet the requirements of the BM Trada scheme for Fire Doors and Doorsets (to BS 476 part 22 or BS EN 1634-1). Include combined smoke seals and intumescent strip set in the frame, hardwood lipped, pair and half FD30 rated hinges per door, 2nr SAA kick plates, 4nr 76mm diameter metal screw fixed 'fire Door keep Shut' signage, supply and fix 1nr FD30 Briton door closer to RHS door (2003V with silver arm / cover (Doorsets: Leaderflush Shapland / Premdor or similar approved and certified by BWF-Certifire or BM Trada Q-Mark). Supply and fix 2nr new fire rated lever handles to RHS leaf and Union mortice lock 'suited' key to match the existing. Include for 2nr new fire safe tower bolts the the passive leaf.	Item			
C	Supply and mechanically fix new softwood architraves to match the existing in all respects.	Item			
<b><u>Decorations</u></b>					
D	Prepare and decorate the new door, door and combination frame and architraves with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC.	Item			
<b><u>Miscellaneous</u></b>					
E	Supply and fix 2nr fingerguards to match the existing.	Item			
F	Include for temporary removal and reinstating the storage and the pull-down projector screen.	Item			
2004170		TO COLLECTION	£		
3/19					

<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>					
<b><u>SCHEDULE OF WORKS</u></b>					
<b><u>DOOR G19 (Plant Room 3)</u></b>					
A	Carefully strip out the existing door, door frame and architraves and dispose from site. Make good all disturbed surfaces.	Item			
B	Supply and fix a new FD30 certified door set comprising new 44mm thick paint finish door (& softwood door frame) to meet the requirements of the BM Trada scheme for Fire Doors and Doorsets (to BS 476 part 22 or BS EN 1634-1). Include combined smoke seals and intumescent strip set in the frame, hardwood lipped, pair and half FD30 rated hinges, 1nr SAA kick plate, supply and fix 1nr FD30 Briton door closer (2003V with silver arm / cover, 1nr screw fixed 'Fire Door Keep Locked Sign', (Doorsets: Leaderflush Shapland / Premdor or similar approved and certified by BWF-Certifire or BM Trada Q-Mark). Supply and fix 2nr new fire rated lever handles and Union mortice lock 'suited' key to match the existing.	Item			
C	Supply and mechanically fix new softwood architraves to match the existing in all respects.	Item			
D	Supply and fix 2nr Rockwool FirePro intumescent pipe collars (1nr on the end of each 100mm PVC vent pipe) to achieve 1hr fire resistance. Rockwool <a href="http://www.rockwool.co.uk">www.rockwool.co.uk</a>	Item			
E	Supply and fix 1nr Rockwool FirePro intumescent pipe collar (45mm diameter - check before purchase) in the WC to achieve 1hr fire resistance. Rockwool <a href="http://www.rockwool.co.uk">www.rockwool.co.uk</a>	Item			
<b><u>Plasterboard &amp; Skim</u></b>					
F	Overboard the existing plasterboard ceiling with new 12mm Gypsum fire board and skim with plaster. Include for temporary removal of light fitting and smoke detector head. On completion re-fix and leave good working order. Allow for commissioning the smoke detector head.	Item			
2004170		TO COLLECTION	£		
3/20					

## FIRE SAFETY UPGRADE

### STANSFIELD HALL PRIMARY SCHOOL

## SCHEDULE OF WORKS

## Decorations

- |   |   |      |
|---|---|------|
| A | Prepare and decorate the new door, door frame and architraves with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC. | Item |
| B | Prepare and decorate the new plaster ceiling with 3nr coats of matt emulsion. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour White.   | Item |
| C | Seal around the PVC waste pipe into the toilet with Rockwool FirePro intumescent sealant.   | Item |

2004170

TO COLLECTION £

<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>  <b><u>SCHEDULE OF WORKS</u></b>  <b><u>DOOR G20 (Storage 23)</u></b> A No work required (2021 Project)  <b><u>DOOR G21 (Cloakroom 2)</u></b> B No work required (2021 Project)  <b><u>DOOR G22 (Teaching 5)</u></b> C No work required (2021 Project)  <b><u>DOOR G23 (Resources 6)</u></b> D No work required (2021 Project)  <b><u>DOOR 24 (Hall 21)</u></b> E No work required (2021 Project)  <b><u>DOOR G25 (Store 8)</u></b> F No work required (2021 Project)  <b><u>DOOR G26 (Store 54)</u></b> G No work required (2021 Project)  <b><u>DOOR G27 (Head 47)</u></b> H No work required (2021 Project)  <b><u>DOOR G28 (Store 9)</u></b> I No work required (2021 Project)				
2004170	3/22	TO COLLECTION	£	

<u>FIRE SAFETY UPGRADE</u>				
<u>STANSFIELD HALL PRIMARY SCHOOL</u>				
<u>SCHEDULE OF WORKS</u>				
A	<u>DOOR G29 (WC 15)</u>			
	No work required			
B	<u>DOOR G30 (WC 14)</u>			
	No work required			
C	<u>DOOR G31 (WC 101)</u>			
	No work required			
D	<u>DOOR G32 (Teaching 17)</u>			
	No work required			
E	<u>DOOR G33 (WC 102)</u>			
	No work required			
F	<u>DOOR G34 (Resources 58)</u>			
	No work required			
G	<u>DOOR G35 (Library 24)</u>			
	No work required			
H	<u>DOOR G36 (WC 4)</u>			
	No work required			
I	<u>DOOR G37 (Resources 6)</u>			
	No work required			
J	<u>DOOR G38 (Teaching 5)</u>			
	No work required			
K	<u>DOOR G39 (Circulation 12)</u>			
	No work required			

<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>					
<b><u>SCHEDULE OF WORKS</u></b>					
<b><u>LOWER FLOOR LEVEL</u></b>					
<b><u>DOOR B1 (Circulation 42)</u></b>					
A	Strip out existing door and door frame and dispose from site. Set aside signage and fingerguard for re-use.	Item			
<b><u>Joinery</u></b>					
B	Supply and fix a new FD30 certified door set comprising new 44mm thick paint finish door (& softwood door frame) to meet the requirements of the BM Trada scheme for Fire Doors and Doorsets (to BS 476 part 22 or BS EN 1634-1). Include combined smoke seals and intumescent strip set in the frame, hardwood lipped, pair and half FD30 rated hinges, 1nr SAA kick plates, 1nr SAA pull handle, 1nr SAA push plate, supply and fix 1nr FD30 Briton door close (2003V with silver arm / cover, 2nr 76mm diameter metal screw fixed 'Fire Door KeepShut' signs. (Doorsets: Leaderflush Shapland / Premdor or similar approved and certified by BWF-Certifire or BM Trada Q-Mark). Reinstate existing signage and fingerguard.	Item			
<b><u>Decorations</u></b>					
C	Prepare and decorate the new door and door frame with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC.	Item			
2004170		TO COLLECTION	£		
3/24					



<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>  <b><u>SCHEDULE OF WORKS</u></b>  <b><u>DOOR B2 (Caretaker 40)</u></b>					
A	Strip out existing door and door frame and dispose from site. Set aside signage for re-use. Carefully strip out the door security contacts and set aside for re-use.	Item			
B	<b><u>Joinery</u></b> Supply and fix a new FD30 certified door set comprising new 44mm thick paint finish door (& softwood door and fanlight frame) to meet the requirements of the BM Trada scheme for Fire Doors and Doorsets (to BS 476 part 22 or BS EN 1634-1). Include combined smoke seals and intumescent strip set in the frame, hardwood lipped, pair and half FD30 rated hinges, 1nr SAA kick plate, 1nr SAA pull handle, 1nr SAA push plate, Georgian wired fanlight) using fire & heat resistant glazing (Kitemarked) using an intumescent glazing / bedding system, supply and fix 1nr FD30 Briton door close (2003V with silver arm / cover, 2nr 76mm diameter screw fixed 'Fire Door Keep Shut' signs. (Doorsets: Leaderflush Shapland / Premdor or similar approved and certified by BWF-Certifire or BM Trada Q-Mark). Supply and fix new Union mortice lock with escutcheon and 'suited' key to match the existing.	Item			
C	Supply and mechanically fix new softwood architraves to match the existing in all respects.	Item			
D	<b><u>Decorations</u></b> Prepare and decorate the new door, door frame and architraves with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC.	Item			
E	<b><u>Miscellaneous</u></b> Refix door alarm contacts and leave in good working order. Include for all connections.	Item			
2004170		TO COLLECTION	£		
3/25					

<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>  <b><u>SCHEDULE OF WORKS</u></b>  <b><u>DOOR B3 (Plant Room 39)</u></b>					
A	Strip out existing door, door frame and architraves and dispose from site.	Item			
B	<b><u>Joinery</u></b> Supply and fix a new FD30 certified door set comprising new 44mm thick paint finish door (& softwood door frame) to meet the requirements of the BM Trada scheme for Fire Doors and Doorsets (to BS 476 part 22 or BS EN 1634-1). Include combined smoke seals and intumescent strip set in the frame, hardwood lipped, pair and half FD30 rated hinges, 1nr SAA kick plate 1nr 76mm diameter metal screw fixed 'Fire Door Keep Locked' sign. (Doorsets: Leaderflush Shapland / Premdor or similar approved and certified by BWF-Certifire or BM Trada Q-Mark). Supply and fix 1nr mortice lock and 2nr lever handles with keyhole. Suite lock to match existing key.	Item			
C	Supply and mechanically fix new softwood architraves to match the existing in all respects.	Item			
D	<b><u>Decorations</u></b> Prepare and decorate the new door, door frame and architraves with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC.	Item			
E	<b><u>Miscellaneous</u></b> Supply and fix 4nr 100mm diameter Rockwool Firepro intumescent collar around the 2nr PVC ventilation pipes. Include for carrying out modifications to the blockwork wall and to the ducts themselves within the Plant Room to allow fire collars to be fitted.	Item			
2004170		TO COLLECTION	£		
	3/26				

<b><u>FIRE SAFETY UPGRADE</u></b>					
<b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>					
<b><u>SCHEDULE OF WORKS</u></b>					
<b><u>DOOR B4 (Boiler 37)</u></b>					
A	Strip out existing door, door frame and architraves and dispose from site.	Item			
<b><u>Joinery</u></b>					
B	Supply and fix a new FD60 certified door set comprising new 54mm thick paint finish door (& softwood door frame) to meet the requirements of the BM Trada scheme for Fire Doors and Doorsets (to BS 476 part 22 or BS EN 1634-1). Include combined smoke seals and intumescent strip set in the frame, hardwood lipped, pair and half FD60 rated hinges, supply and fix 1nr FD60 Briton door close (2003V with silver arm / cover, 1nr SAA kick plate 2nr 76mm diameter metal screw fixed fire door keep shut signs. (Doorsets: Leaderflush Shapland / Premdor or similar approved and certified by BWF-Certifire or BM Trada Q-Mark). Supply and fix 1nr mortice lock and 2nr lever handles with keyhole. Suite lock to match existing key.	Item			
C	Supply and mechanically fix new softwood architraves to match the existing in all respects.	Item			
<b><u>Decorations</u></b>					
D	Prepare and decorate the new door, door frame and architraves with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC.	Item			
2004170		TO COLLECTION	£		
3/27					

A	<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>  <b><u>SCHEDULE OF WORKS</u></b>  <b><u>DOOR B5 (Storage 36)</u></b> No work required (2021 Project)				
	2004170	<u>TO COLLECTION</u>	£		

<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>  <b><u>SCHEDULE OF WORKS</u></b>  <b><u>DOOR B6 (Circulation 43)</u></b>					
A	Strip out existing door, door frame and architraves and dispose from site. Stand alone panel and timber frame over door to remain.	Item			
<b><u>Joinery</u></b>					
B	Supply and fix a new FD30 certified door set comprising new 44mm thick paint finish door (& softwood door frame) to meet the requirements of the BM Trada scheme for Fire Doors and Doorsets (to BS 476 part 22 or BS EN 1634-1). Include combined smoke seals and intumescent strip set in the frame, hardwood lipped, pair and half FD30 rated hinges, 1nr SAA kick plate, 1nr 76mm diameter metal screw fixed 'Fire Door Keep Locked' sign. (Doorsets: Leaderflush Shapland / Premdor or similar approved and certified by BWF-Certifire or BM Trada Q-Mark). Supply and fix 1nr mortice lock and 2nr lever handles with keyhole. Suite lock to match existing key.	Item			
C	Supply and mechanically fix new softwood architraves to match the existing in all respects.	Item			
<b><u>Decorations</u></b>					
D	Prepare and decorate the new door, door frame and architraves with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC.	Item			
<b><u>Miscellaneous</u></b>					
E	Supply and fix 12mm Gypsum fire board and 3mm plaster skim on the rear of the panel over the door within the store room.	Item			
F	Isolate and make safe the electrical cable over the door panel and remove the existing PVC conduit where it passes through the partition wall only. Supply and fix new Polypipe FireBreak Electric Conduit 25mm x 300mm - 25C89. Ref: CB19054 <a href="http://www.cpc.farnell.com">www.cpc.farnell.com</a> Refix electric cables include for all connections (and commissioning if cable serves a smoke detector head).	Item			
2004170		TO COLLECTION	£		
3/29					

<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>					
<b><u>SCHEDULE OF WORKS</u></b>					
<b><u>DOOR B7 (Circulation 44)</u></b>					
A	Strip out existing double doors, fanlight frame, architraves and dispose from site. Strip off signage and fingerguards and set aside for reuse.	Item			
<b><u>Joinery</u></b>					
B	Supply and fix a new FD30 certified double door set comprising new 44mm thick paint finish door (& softwood door and fanlight frame) to meet the requirements of the BM Trada scheme for Fire Doors and Doorsets (to BS 476 part 22 or BS EN 1634-1). Include combined smoke seals and intumescent strip set in the frame, hardwood lipped (square edged on leading edge, 3nr pairs FD30 rated hinges, 4nr SAA kick plates, 2nr SAA pull handles, 2nr SAA push plates, 2nr clear FD30 fire safe and toughened safety glass vision panels per door leaf, 1nr clear FD30 fire safe fanlight glazing all using fire & heat resistant glazing (Kitemarked) using an intumescent glazing / bedding system, supply and fix 2nr FD30 Briton door closers (2003V with silver arm / cover, 4nr 76mm diameter screw fixed 'Fire Door Keep Shut' signs. (Doorsets: Leaderflush Shapland / Premdor or similar approved and certified by BWF-Certifire or BM Trada Q-Mark)	Item			
C	Supply and mechanically fix new softwood architraves to match the existing in all respects.	Item			
<b><u>Decorations</u></b>					
D	Prepare and decorate the new doors, door frame and architraves with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC.	Item			
E	Prepare and decorate the previously painted plasterboard partition wall with 2nr coats emulsion. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour: As existing.	Item			
<b><u>Miscellaneous</u></b>					
F	Apply a neatly tooled smooth bead of Rockwool Acoustic Intumescent Mastic around the plasterboard partition where scribed around the stonework wall (both sides of partition). All work to be in accordance with the manufacturer's instructions.	Item			
G	Refix the stick-on Running Man directional signage on the new fanlight glazing.	Item			
H	Refix the previously set aside fingerguards.	Item			
2004170		TO COLLECTION		£	
3/30					

<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>  <b><u>SCHEDULE OF WORKS</u></b>  <b><u>DOOR B8 (Staff Room 30)</u></b>					
A	Strip out existing door, door frame and architraves and dispose from site. Strip off signage and fingerguards and set aside for reuse.	Item			
B	<b><u>Joinery</u></b> Supply and fix a new FD30 certified door set comprising new 44mm thick paint finish door (& softwood door frame) to meet the requirements of the BM Trada scheme for Fire Doors and Doorsets (to BS 476 part 22 or BS EN 1634-1). Include combined smoke seals and intumescent strip set in the frame, hardwood lipped, pair and half FD30 rated hinges, 1nr SAA kick plate, 2nr 76mm diameter metal screw fixed 'Fire Door Keep Shut' signs. 2nr obscured FD30 fire safe and toughened safety glass vision panels using fire & heat resistant glazing (Kitemarked) using an intumescent glazing / bedding system, supply and fix 1nr FD30 Briton door closer (2003V with silver arm / cover, (Doorsets: Leaderflush Shapland / Premdor or similar approved and certified by BWF-Certifire or BM Trada Q-Mark). Supply and fix 1nr mortice lock and 2nr lever handles with thumbturn. Suite lock to match existing key.	Item			
C	Supply and mechanically fix new softwood architraves to match the existing in all respects.	Item			
D	<b><u>Decorations</u></b> Prepare and decorate the new door, door frame and architraves with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC.	Item			
E	Refix the previously set aside fingerguards and signage.	Item			
2004170		TO COLLECTION	£		
3/31					

<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>  <b><u>SCHEDULE OF WORKS</u></b>  <b><u>DOOR B9 (Plant Room 32)</u></b>					
A	Strip out existing door, door frame and architraves and dispose from site.	Item			
B	<b><u>Joinery</u></b> Supply and fix a new FD30 certified door set comprising new 44mm thick paint finish door (& softwood door frame) to meet the requirements of the BM Trada scheme for Fire Doors and Doorsets (to BS 476 part 22 or BS EN 1634-1). Include combined smoke seals and intumescent strip set in the frame, hardwood lipped, pair and half FD30 rated hinges, 1nr SAA kick plate 1nr 76mm diameter metal screw fixed 'Fire Door Keep Locked' sign. (Doorsets: Leaderflush Shapland / Premdor or similar approved and certified by BWF-Certifire or BM Trada Q-Mark). Supply and fix 1nr mortice lock and 2nr lever handles with keyhole. Suite lock to match existing key.	Item			
C	Supply and mechanically fix new softwood architraves to match the existing in all respects.	Item			
D	<b><u>Decorations</u></b> Prepare and decorate the new door, door frame and architraves with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC.	Item			
E	<b><u>Miscellaneous</u></b> Within the next door Meeting Room carefully open up the boxing-in over the PVC vent pipe and set aside for re-use. Remove the PVC pipes where they enter the Plant Room and dispose. Supply and fix 2nr new PVC pipe projections into the Plant Room (projections to be 120mm). Refix plasterboard in Meeting Room.	Item			
F	Supply and fix 4nr 100mm diameter Rockwool Firepro intumescent collar around the 2nr PVC ventilation pipes. Include for carrying out modifications to the blockwork wall and to the ducts themselves within the Plant Room to allow fire collars to be fitted. All work to be in accordance with the manufacturer's instructions.	Item			
2004170		TO COLLECTION	£		
3/32					



<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>					
<b><u>SCHEDULE OF WORKS</u></b>					
<b><u>DOOR B10 (Meeting Room 31)</u></b>					
A	Strip out existing door, door frame and architraves and dispose from site. Strip off signage and fingerguards and set aside for reuse.	Item			
<b><u>Joinery</u></b>					
B	Supply and fix a new FD30 certified door set comprising new 44mm thick paint finish door (& softwood door frame) to meet the requirements of the BM Trada scheme for Fire Doors and Doorsets (to BS 476 part 22 or BS EN 1634-1). Include combined smoke seals and intumescent strip set in the frame, hardwood lipped, pair and half FD30 rated hinges, 1nr SAA kick plate, 2nr 76mm diameter metal screw fixed 'Fire Door Keep Shut' signs. 2nr obscured FD30 fire safe and toughened safety glass vision panels using fire & heat resistant glazing (Kitemarked) using an intumescent glazing / bedding system, supply and fix 1nr FD30 Briton door closer (2003V with silver arm / cover, (Doorsets: Leaderflush Shapland / Premdor or similar approved and certified by BWF-Certifire or BM Trada Q-Mark). Supply and fix 1nr mortice lock and 2nr lever handles. Suite lock to match existing key.	Item			
C	Supply and mechanically fix new softwood architraves to match the existing in all respects.	Item			
<b><u>Decorations</u></b>					
D	Prepare and decorate the new door, door frame and architraves with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC.	Item			
E	Prepare and decorate the previously painted plasterboard boxing in around the vent pipes to the next door Plant Room with 2nr coats emulsion paint. Dulux paint. Colour: to match existing.	Item			
<b><u>Miscellaneous</u></b>					
F	Refix the signage and fingerguards previously set aside.	Item			
2004170		TO COLLECTION		£	
3/33					

<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>  <b><u>SCHEDULE OF WORKS</u></b>  <b><u>DOORS B11 (Dining Room 34)</u></b>					
A	Carefully strip out the timber wall cladding at the door opening back to the bare plaster and dispose from site. Skim where required (allow 0.5m2) to ensure new fire resistant door frame is not sat on flammable material. Make good remaining timber cladding to the walls around the new doors.	Item			
B	Supply and fix a new FD60 certified double door set (see contract drawing) comprising new 54mm thick paint finish doors 600mm wide per leaf x 2040mm high (& softwood combination frame) to meet the requirements of the BM Trada scheme for Fire Doors and Doorsets (to BS 476 part 22 or BS EN 1634-1). Include combined smoke seals and intumescent strip set in the frame, hardwood lipped, pair and half FD60 rated hinges, 4nr SAA kick plates, 2nr SAA pull handles, 2nr SAA push plates, 4nr clear FD60 toughened vision panels (and fanlight / side panels) using fire & heat resistant glazing (Kitemarked) using an intumescent glazing / bedding system, 2nr screw fixed 'Fire Door Keep Clear' signs. (Doorsets: Leaderflush Shapland / Premdor or similar approved and certified by BWF-Certifire or BM Trada Q-Mark). Supply and fix 2nr fingerguards. Note: doors to project into corridor as little as possible & certainly no more than 30mm)	Item			
C	Supply and mechanically fix new softwood architraves to match the existing in all respects.	Item			
D	Prepare and decorate the new plaster wall finish with 3nr coats Dulux emulsion to match the existing in all respects. All work to be in accordance with the manufacturers instructions.	Item			
<b><u>DECORATIONS</u></b>					
E	Prepare and decorate the new door, door frame and architraves with knotting, 1nr coat primer, 2nr undercoat and 1nr gloss coat. All work to be in accordance with the manufacturer's instruction. Dulux Paints, Colour TBC.	Item			
<b><u>ELECTRICAL</u></b>					
F	To the new double doors supply and fix (transom fixed) 2nr new Dorma TS 73 EMF electromagnetic hold open devices. Supply and fix 2nr additional distributor boxes and 'red' override manual release push-button and 'Close door' signage. Override to be located approx 1.5m above floor level in the immediate vicinity of the door (this must not be hidden when the door is in its hold-open position). Connect to fire alarm system and commission. All work to be in accordance with the manufacturer's instructions. Dorma Kaba Tel: 07933 092 241 alexander.hume@dormakaba.com	Item			
2004170		TO COLLECTION		£	
3/34					

<b><u>FIRE SAFETY UPGRADE</u></b> <b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>  <b><u>SCHEDULE OF WORKS</u></b>  <b><u>ELECTRICAL (CONT)</u></b>					
A	To the new double doors supply and fix 1nr new Dorma PSU-8 power supply units. All work to be in accordance with the manufacturer's instructions. Dorma Kaba Tel: 07933 092 241 alexander.hume@dormakaba.com	Item			
B	To the new double doors supply and fit 1nr new 230V fused spur electricity supply to power the door hold open devices. Include for all necessary feeds, connections and conduit. Make good all disturbed surfaces. Location to be agreed on site.	Item			
<b><u>MISCELLANEOUS</u></b>					
C	Supply and fix to the internal face of the over door glazed panel, 1nr Nite-Glo Fire Exit Running Man Right & Arrow Down Signs. Seton Signage Tel: 0800 316 6933 www.seton.co.uk	Item			
D	Supply and mechanically fix to the floor 2nr stainless steel door protectors 1100mm high x 420mm wide x 50-60mm tubular steel (in an 'A' frame configuration) as per drawing.	Item			
2004170		TO COLLECTION	£		
3/35					

<b><u>FIRE SAFETY UPGRADE</u></b>					
<b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>					
<b><u>SCHEDULE OF WORKS</u></b>					
<b><u>DOOR B12 (Kitchen 35)</u></b>					
A	No work required				
<b><u>DOOR B13 (WC 26)</u></b>					
B	No work required				
<b><u>DOOR B14 (Circulation 45)</u></b>					
C	No work required				
<b><u>DOOR B15 (Circulation 46)</u></b>					
D	No work required				
<b><u>DOOR B16 (Storage 41)</u></b>					
E	No work required				
<b><u>INTERNAL FIRE STOPPING / COMPARTMENTATION</u></b>					
F	A specialised sub-contractor is to provide 30 & 60 mins fire compartmentation in various locations and provide certification on completion. Use Rockwool FirePro Acoustic Intumescent sealant / High Expansion Intumescent Sealant. All work in accordance with the manufacturer's instructions. Under no circumstance must pink fire foam be used. See enclosed quote from preferred company North West Fire protection or equal and approved				
		Item			
	Email: customersupportcentre@rockwool.co.uk Telephone: 01656 868 400				
G	Clean down dust and sweep all areas on completion of all the works contained within this specification.				
		Item			
H	Supply and mechanically screw fix 21nr FD30S & 2nr FD60S heavy duty PVC 'Fire Door Identification Discs' (45mm diameter x 1mm thick with white lettering on a brown background) on the hinged edge side of each newly fitted fire door (100mm down from top of door and 100mm in from hinged edge to the centre of the disc). Tel: 01215 212179 sales@fireandacousticseals.co.uk www.fireandacousticseals.co.uk/Fire-Identification-Discs				
		Item			
2004170		TO COLLECTION		£	
3/36					

	<b><u>FIRE SAFETY UPGRADE</u></b>			
	<b><u>STANSFIELD HALL PRIMARY SCHOOL</u></b>			
	<b><u>SCHEDULE OF WORK</u></b>			
	<b><u>COLLECTION</u></b>			
	From page Nr 3/1			
	From page Nr 3/2			
	From page Nr 3/3			
	From page Nr 3/4			
	From page Nr 3/5			
	From page Nr 3/6			
	From page Nr 3/7			
	From page Nr 3/8			
	From page Nr 3/9			
	From page Nr 3/10			
	From page Nr 3/11			
	From page Nr 3/12			
	From page Nr 3/13			
	From page Nr 3/14			
	From page Nr 3/15			
	From page Nr 3/16			
	From page Nr 3/17			
	From page Nr 3/18			
	From page Nr 3/19			
	From page Nr 3/20			
	From page Nr 3/21			
	From page Nr 3/22			
	From page Nr 3/23			
2004170		TO COLLECTION	£	
	3/37			

**COLLECTION (CONT)**

From page Nr 3/36

3/38