



ARCHITECTURAL EMPORIUM Ltd EMAIL: mail@architectural-emporium .co.uk WEB: www.architectural-emporium .co.uk ADDRESSI3 Hope St, Liverpool, L1 9BQ PHONE: +44 (0)151 363 0000

Damage to render likely caused by lack of rainwater pipe above or insufficient - coping overhang

Existing UVPC double glazed windows

Existing single glazed timber windows – with top hung openers.

Existing cementitious render with white painted finish

Existing blocked up openings





- Existing blocked up openings

Existing cementitious render

EX.02



- Existing window cill

FOR: PLANNING
CHECKED BY:TW | DRAWN BY: MS
SCALE: NTS
PAPER SIZE: A4

JOB: NEW ISLINGTON MILL No. 294

**0.551\_Rev** *FIRST ISSUE: 24.01.19* 

PHOTO APPENDIX\_01

EX.03





ARCHITECTURAL EMPORIUM Ltd EMAIL: mail@architectural-emporium .co.uk WEB: www.architectural-emporium .co.uk ADDRESSI3 Hope St, Liverpool, L1 9BQ PHONE: +44 (0)151 363 0000

Existing parapet to corner building in need of structural repairs

Existing eastern gable





Existing water tower of Wilmington Mill behind

- Existing Engine house

Existing corner building

Existing low level arched openings behind vehicle

EX.06

FOR: PLANNING
CHECKED BY:TW | DRAWN BY: MS
SCALE: NTS

PAPER SIZE: A4

JOB: NEW ISLINGTON MILL No. 294

**0.552\_Rev** *FIRST ISSUE: 24.01.19* 



ARCHITECTURAL EMPORIUM Ltd EMAIL: mail@architectural-emporium .co.uk WEB: www.architectural-emporium .co.uk ADDRESSI3 Hope St, Liverpool, L1 9BQ PHONE: +44 (0)151 363 0000

- Existing extract to be removed

Existing single storey outrigger to be demolished with all redundant services - removed

EX.07





Existing soil vent pipe to be removed

Existing single storey outrigger to be demolished with all redundant services removed

Existing chimney stack in need of repairs. Refer to condition survey for further details

EX.08 EX.09



Existing timber goods door with lifting beam above.

 Existing stables. Refer to ownership plan 0.004

— Typical existing external lighting

Existing refuse arrangements

FOR: PLANNING
CHECKED BY:TW | DRAWN BY: MS
SCALE: NTS
PAPER SIZE: A4


JOB: NEW ISLINGTON MILL No. 294

**0.553\_Rev** *FIRST ISSUE: 24.01.19* 

PHOTO APPENDIX\_03

EX.10





ARCHITECTURAL EMPORIUM Ltd EMAIL: mail@architectural-emporium .co.uk WEB: www.architectural-emporium .co.uk ADDRESSI3 Hope St, Liverpool, L1 9BQ PHONE: +44 (0)151 363 0000

Existing timber goods door with lifting beam above.

Existing painted signage to be retained

- Existing refuse arrangements

EX.11 EX.12



Existing failing rain water goods.

- Existing timber single glazed windows

Existing blocked up window openings with temporary artwork infront

Existing soil vent pipe to be removed

Existing timber shed to be removed

Existing shared courtyard

EX.13





- Existing soil vent pipes to be removed.

Existing cantilevered structure

Existing cobbles to courtyard.

Existing main entrance to building.

FOR: PLANNING
CHECKED BY:TW | DRAWN BY: MS
SCALE: NTS
PAPER SIZE: A4

JOB: NEW ISLINGTON MILL No. 294


**0.554\_Rev** *FIRST ISSUE: 24.01.19* 

PHOTO APPENDIX\_04

EX.14 EX.15




EX.18







EX.19





Existing main entrance to building.

- Existing fire escape

Existing non compliant steel fire escape stair.

FOR: PLANNING CHECKED BY:TW | DRAWN BY: MS SCALE: NTS PAPER SIZE: A4

JOB: NEW ISLINGTON MILL No. 294

0.555\_Rev





# (Ê)

#### NEW ISLINGTON MILL No. 294

ARCHITECTURAL EMPORIUM Ltd EMAIL: mail@architectural-emporium .co.uk WEB: www.architectural-emporium .co.uk ADDRESSI3 Hope St, Liverpool, L1 9BQ PHONE: +44 (0)151 363 0000

- Existing soil vent pipes to be removed

- Typical north elevation failing rain water pipe to be replaced. Existing masonry behind to be repointed where required using matching lime render with mortar beds to match the existing.

EX.20 EX.21



EX.22

FOR: PLANNING
CHECKED BY:TW DRAWN BY: MS
SCALE: NTS
PAPER SIZE: A4

JOB: NEW ISLINGTON MILL No. 294

**0.556\_Rev** *FIRST ISSUE: 24.01.19* 



ARCHITECTURAL EMPORIUM Ltd EMAIL: mail@architectural-emporium .co.uk WEB: www.architectural-emporium .co.uk ADDRESS13 Hope St, Liverpool , L1 9BQ PHONE: +44 (0)151 363 0000

Junction between pitched roof and flat roof of New Islington Mill

Current rain water pooling on flat roof — build up

- Roof lantern felted over

EX.23



Pitched roof of corner unit behind

Existing barbed wire to top of parapet to be removed

Current rain water pooling on flat roof build up. Debris to be removed.

EX.24



 Existing roof access from current lift shaft. No door present.

- Soil vent pipes to be removed

FOR: PLANNING
CHECKED BY:TW | DRAWN BY: MS
SCALE: NTS
PAPER SIZE: A4

JOB: NEW ISLINGTON MILL No. 294

**0.557\_Rev** *FIRST ISSUE: 24.01.19* 





ARCHITECTURAL EMPORIUM Ltd
EMAIL: mail@architectural-emporium .co.uk
WEB: www.architectural-emporium .co.uk
ADDRESS/31 Alope St, Liverpool, L1 9BQ
PHONE: +44 (0)151 363 0000

Existing pitched roof with numerous repairs over existing roof slates

- Existing valley gutter to roof

EX.26



- Existing pitched roof from south

EX.27

FOR: PLANNING
CHECKED BY:TW DRAWN BY: MS
SCALE: NTS
PAPER SIZE: A4

JOB: NEW ISLINGTON MILL No. 294

0.558\_Rev









NEW ISLINGTON MILL No. 294

ARCHITECTURAL EMPORIUM Ltd

Existing building services at ground floor level.

Existing typical corridor at ground floor level

Existing exposed concrete floor finish

Existing entrance from south elevation

Existing lift shaft not in use




INT.03



INT.04



INT.05



INT.06

Existing typical vinyl floor finish

FOR: PLANNING CHECKED BY:TW | DRAWN BY: MS SCALE: NTS PAPER SIZE: A4

JOB: NEW ISLINGTON MILL No. 294

0.559\_Rev FIRST ISSUE: 24.01.19






INT.09



INT.11



**INT.08** 



INT.10



Existing typical corridor to ground and second floors with cellular rehearsal rooms off.

NEW ISLINGTON MILL No. 294


ARCHITECTURAL EMPORIUM Ltd EMAIL: mail@architectural-emporium .co.uk WEB: www.architectural-emporium .co.uk ADDRESS13 Hope St, Liverpool , L1 9BQ PHONE: +44 (0)151 363 0000

Existing main staircase with vinyl floor finish and steel nosings to be removed and replaced

FOR: PLANNING
CHECKED BY:TW | DRAWN BY: MS
SCALE: NTS

PAPER SIZE: A4 JOB: NEW ISLINGTON MILL No. 294

**0.560\_Rev** *FIRST ISSUE: 24.01.19* 






ARCHITECTURAL EMPORIUM Ltd
EMAIL: mail@architectural-emporium .co.uk
WEB: www.architectural-emporium .co.uk
ADDRESS13 Hope St, Liverpool , L1 9BQ
PHONE: +44 (0)151 363 0000

- Existing suspended ceiling grid

Existing open plan first floor showing buildings current structural arrangement

INT.12





Existing masonry wall sandblasted and sealed with existing timber floor boards sanded and treated.

INT.13



INT.14



- Existing typical first floor corridor


INT.15 INT.16

FOR: PLANNING
CHECKED BY:TW | DRAWN BY: MS
SCALE: NTS
PAPER SIZE: A4

JOB: NEW ISLINGTON MILL No. 294

0.561\_Rev







ARCHITECTURAL EMPORIUM Ltd EMAIL: mail@architectural-emporium .co.uk WEB: www.architectural-emporium .co.uk ADDRESS13 Hope St, Liverpool , L1 9BQ PHONE: +44 (0)151 363 0000


Typical sanitary facilities across all floors.

INT.17 INT.18

FOR: PLANNING
CHECKED BY:TW DRAWN BY: MS
SCALE: NTS

PAPER SIZE: A4 JOB: NEW ISLINGTON MILL No. 294

0.562\_Rev






ARCHITECTURAL EMPORIUM Ltd EMAIL: mail@architectural-emporium .co.uk WEB: www.architectural-emporium .co.uk ADDRESSI3 Hope St, Liverpool, L1 9BQ PHONE: +44 (0)151 363 0000

Existing wood wool (or similar) acoustic panels to ceiling

Existing timber roof lantern structure above

Existing steel beam roof structure.

INT.19



- Existing steel roof structure.

FOR: PLANNING
CHECKED BY:TW DRAWN BY: MS
SCALE: NTS

PAPER SIZE: A4 JOB: NEW ISLINGTON MILL No. 294

0.563\_Rev