



FOLKESTONE TOWN COUNCIL

Folkestone Play Parks Upgrade Brief Document – Parks Information

Introduction

Folkestone Town Council are responsible for several play parks around the town. As part of investing in the health and well-being of the residents of Folkestone a budget has been made available to upgrade eight of these parks.

The following has been proposed.

| Park | Proposed budget |
|-----------------------|-----------------|
| Coniston Road | £27,000.00 |
| Downs Road | £35,000.00 |
| Firs Lane | £27,000.00 |
| George Gurr | £25,000.00 |
| Naseby Ave | £1,000.00 |
| Pine Way | £25,000.00 |
| Roman Way | £50,000.00 |
| Southern Way | £40,000.00 |
| | |
| Total proposed budget | £230,000.00 |



The council are looking to maximise the play equipment and play opportunities at each site through this project. We are seeking a contractor with experience in play parks to partner with the council to make this work.

This document should be read in conjunction with the following as part of the tender pack:

- 3064-Folkestone Parks Refurbishment Preliminaries -2022-04-28
- ITQ Instructions Document Main Contractor Folkestone Play Parks 3064 190422
- ITQ Response Document Main Contractor Folkestone Play Parks 3064 190422

In addition, there are sets of photos for each park that can be found on this link.

https://www.dropbox.com/sh/napx1kzqyw9rq1x/AACsNHgjiE3mqtTHP3WMPTe1a?dl=0

Where possible the council would like to minimise waste across the works and recycle as much as possible. There may be opportunities to move serviceable equipment from one park to another where for example equipment has been installed for the wrong age group.

With respect to Naseby Park this has recently been refitted and we would urge contractors to look at this space for inspiration. There is a small allowance at this park for minor repairs.

With respect to Roman Way Park we would urge contractors to think big here and propose something inspirational for the families living in that area. It will be possible to move proposed budgets around parks as long as the overall figure remains the same.

Parks Information

The following sections give information specific to each park. Please consider these in the light of the overall aims of the project.



Park:Coniston Road ParkAddress:Coniston Road, Folkestone CT19 5JQProposed budget:£27,000

Photo



Context

Coniston Road Park is green space hemmed in by residential property on all sides. It has a range of play equipment in a dedicated play area surrounded green space. It is accessed from the north and south ends. The western section of green space has a number of established and healthy trees that could be incorporated in to the park offer in some way. The lower part of the park has a wild area that could be made more accessible.

Map





| Equipment | Condition |
|---------------|-----------|
| Swings | Remove |
| Rocking horse | Remove |

Contractors are encouraged to suggest replacement and new play equipment that is robust, has proven benefits to users and will enhance the play experience in this park. Attention should be given to the public feedback about this park given later.

Repairs

| | Wet pour floor tiles have failed in the designated play area and need to be taken out completely and another solution found. There is a Bow Top fence surrounding the play area. Repairs are required to both gates and the maintenance gate. Consideration could be given as to whether the fence is required at this location. |
|---------|--|
| | The slide was recently removed as it was rusting and had |
| | become unsafe |
| Desires | |
| | Integrate with the landscape to bring the play, outdoor seating, picnic seating, walkways and wooded area into one cohesive visitor experience. |
| | Develop a design to focus on adventure in nature to perhaps include |
| | balancing, climbing and trails at low level so that grass matting could be |
| | required rather than impact accentuating to enhance the natural aspect of the park. |
| | Is there an opportunity for sensory equipment to be included? |
| | There currently no bins or poo bins. |
| | |

Age range Up to 8

Contractors are encouraged to suggest replacement floor surfaces that are robust, attractive and will enhance the visitor experience in this park.

| Public feedback | |
|--|---------------------------------|
| How do you use the Park? | |
| Walking | 20.00% |
| Dog Walking | 10.00% |
| Childrens Play | 70.00% |
| What facilities would you like to see developed of | or improved at Coniston Road Pa |
| Swings | 88.89% |
| Slide | 88.89% |
| Climb | 77.78% |
| Toddler Play | 44.44% |
| Adventure Play | 88.89% |
| Sensory/inclusive | 22.22% |

Job ref: 3064



| Sports/ Active | 33.33% |
|----------------|--------|
| Landscaping | 33.33% |
| Picnic/seating | 55.56% |

Contractors are encouraged to suggest furniture that is robust, attractive and will enhance the visitor experience in this park. Consideration should be given to provision of litter and poo bins. Where there aren't any these should be provided.

| Park: | Downs Road Park |
|----------|---------------------------------|
| Address: | Downs Road, Folkestone CT19 5TH |
| | |

Proposed budget: £35,000

Photo



Context

Downs Road Park is green space hemmed in by developments and the main ring road for the town. It has a range of play equipment in a dedicated play area surrounded largely blocks of flats. It is accessed through Downs Road and is a densly populated residential area. The open space is quite sloped and has a range of different surfaces and uses.

Мар





| Equipment | Condition |
|--------------------------|-----------|
| Climbing frame and slide | Repair |
| Swings | Good |

Contractors are encouraged to suggest replacement and new play equipment that is robust, has proven benefits to users and will enhance the play experience in this park. Attention should be given to the public feedback about this park given later in this report.

This park has space for more equipment as some pieces have been removed over the years. The bulk of the designated play area floor is tarmac. This is unfriendly and grim and needs to be replaced or overlaid with something softer and more colourful. Contractors are encouraged to suggest replacement floor surfaces that are robust, attractive and will enhance the visitor experience in this park. There are some rusty posts to be removed.

Public feedback

| 10.00% |
|--------|
| 10.00% |
| 60.00% |
| 20.00% |
| Road |
| |
| 50.00% |
| 60.00% |
| 70.00% |
| 60.00% |
| 60.00% |
| 40.00% |
| 10.00% |
| |



| Landscaping | 20.00% |
|----------------|--------|
| Picnic/seating | 30.00% |
| other | 30.00% |

The emphasis for this space for new equipment should be towards 2–8-year-olds. Toddler and adventure play would seem to be the most popular desires.

Contractors are encouraged to suggest furniture that is robust, attractive and will enhance the visitor experience in this park. Consideration should be given to provision of litter and poo bins. Where there aren't any these should be provided.

Park: Firs Lane Park

Address: Firs Lane, Folkestone CT19 4QE

Proposed budget: £27,000

Photo



Context

Firs Lane Park is green space in the middle of a large residnetial area. It has a range of play equipment in a dedicated play area and has a large green open space. It is accessed from all sides and shares the space with some council owned garages. The space has recently been illegally occupied by travellers and so would benefit from some changes to the access routes. For example large boulders could be stretegcally deployed. This would also stop the park being used by cars as a short cut.



Мар



| Equipment | Condition |
|----------------|-----------|
| Slide | Repair |
| Climbing frame | Repair |
| Swings | Remove |
| Goal posts | Replace |
| Benches | Good |

Contractors are encouraged to suggest replacement and new play equipment that is robust, has proven benefits to users and will enhance the play experience in this park. Attention should be given to the public feedback about this park given later in this report.

There is an opportunity in this park for more open play and ball play. Is there space for a half MUGA? This could be against the garages where the broken goalpost is located. This park has opportunities to promote sport.

This park can cater for all ages if the right equipment is selected, and a good plan is put in place. Contractors should be aware that there are Anti-Social Behaviour issues in this park particularly later in the day when younger children have gone home. Consideration needs to be given to equipment and furniture in this regard,

Floor surfaces are mixed, and the grass is bare in places. Attention should be given to robust and attractive flooring in the right places.

| Public feedback | |
|--------------------------|--------|
| How do you use the Park? | |
| Walking | 20.00% |
| Dog Walking | 10.00% |



| Picnic & Sitting | 10.00% |
|---|--------|
| Childrens Play | 60.00% |
| What facilities would you like to see developed or improved at Firs Park? | Lane |
| Swings | 66.67% |
| Slide | 66.67% |
| Climb | 55.56% |
| Toddler Play | 44.44% |
| Adventure Play | 66.67% |
| Sensory/inclusive | 22.22% |
| Sports/ Active | 44.44% |
| Landscaping | 44.44% |
| Picnic/seating | 88.89% |
| | |

| Park: | George Gurr Park |
|------------------|---|
| Address: | George Gurr Crescent, Folkestone CT19 6LG |
| Proposed budget: | £25,000 |

Photo



Context

George Gurr Park is a relateively large open space with a range of play equipment in a dedicated play area surrounded largely by natural countryside. It is accessed through Geaorge Gurr Crescent on the South side which is a residential area. The area is widely populated with families with children of all



ages who use the park at all times. The open space is quite steeply sloped and borders the North Downs

Мар



| Equipment | Condition |
|--------------------------------------|-----------|
| Climbing frame, rope climb and slide | Repair |
| Swings | Remove |

Contractors are encouraged to suggest replacement or new play equipment that is robust, has proven benefits to users and will enhance the play experience in this park. Attention should be given to the public feedback about this park given later in this report. Floor surfaces need attention in the designated play area. New floors should be robust and colourful.

Could the swings be replaced with a warrior swing? This park is used mainly by 2–11-year-olds. Could there be some new equipment for smaller children? Is there space for a half MUGA? Can the steep nature of the open space be used in some way?

This park is bordered by wilderness and a national park (North Downs). Can wildlife feature more strongly in the offer? Could there be an attraction at the top of the slope to encourage children to make the journey to the top?

| Public feedback | |
|---|---------|
| How do you use the Park? | |
| Dog Walking | 40.00% |
| Picnic & Sitting | 10.00% |
| Childrens Play | 40.00% |
| other | 10.00% |
| What facilities would you like to see developed or improved at Geor | ge Gurr |
| Park? | |
| Swings | 88.89% |
| Slide | 55.56% |

Job ref: 3064



| Climb | 44.44% |
|-------------------|--------|
| Toddler Play | 66.67% |
| Adventure Play | 66.67% |
| Sensory/inclusive | 33.33% |
| Sports/ Active | 44.44% |
| Landscaping | 44.44% |
| Picnic/seating | 55.56% |
| other | 11.10% |

Contractors are encouraged to suggest furniture that is robust, attractive and will enhance the visitor experience in this park. Consideration should be given to provision of litter and poo bins. Where there aren't any these should be provided.

Park: Naseby Avenue

Address: Naseby Avenue, Folkestone CT20 3SJ

Proposed budget: £1,000

Photo



Context

Naseby Avenue Park is a small space with a range of play equipment in a dedicated play area and open space covered with grass around. It is bordered on all side by residential properties. The area is widely populated with families with children of all ages who use the park at all times.



Мар



| Equipment | Condition |
|-----------|-----------|
| Swings | Good |
| Slide | Good |
| Springs | Good |

Contractors are encouraged to use this park as a recent example of play possibilities. There is small budget for floor repairs.

Park: Pine Way

Address: Pine Way, Folkestone CT19 4QL

Proposed budget: £25,000

Photo





Context

Pine Way Park is a small space with a range of play equipment and open space covered with grass. It is bordered on all side by residential properties and shares its southerly entrance with Harcourt Primary School. The area is widely populated with families with children of all ages who use the park at all times. The park gets busy with Primary School aged children at school closing times and in to the evening.



Map



| Equipment | Condition |
|----------------|-----------|
| Swings | Remove |
| Roundabout | Good |
| Balancing beam | Good |
| Log steps | Removed |

Contractors are encouraged to suggest replacement play equipment that is robust, has proven benefits to users and will enhance the play experience in this park. Attention should be given to the public feedback about this park given later in this report. . Contractors are encouraged to consider floor surfaces that will enhance the natural visitor experience.

There are some planters that can be removed as they are at the end of their useful life. There are a number of bench bases and no benches. The swings need some attention and may benefit from being moved to a park for older children.

There is an opportunity to develop a design to focus on adventure to include balancing, climbing and trails at low level so that grass matting could be required rather than impact accentuating to enhance the natural aspect of the park. This would benefit the many school children that pass through every school day.

There have been some issues with ball games and balls hitting private fences and causing nuisance. Can new equipment be placed to prevent ball games and encourage other types of play?

Public feedback

| How | do | vou | use | the | Park? |
|--------|----|-----|-----|-----|--------|
| 110 11 | uu | you | usc | unc | i uik; |

| Picnic & Sitting | 10.00% |
|---|------------------|
| Childrens Play | 90.00% |
| What facilities would you like to see developed or impro Park? | oved at Pine Way |
| Climb | 80.00% |
| Toddler Play | 60.00% |
| Adventure Play | 100.00% |
| Sensory/inclusive | 70.00% |
| Landscaping | 40.00% |
| Picnic/seating | 90.00% |
| | |

Contractors are encouraged to suggest furniture that is robust, attractive and will enhance the visitor experience in this park. Consideration should be given to provision of litter and poo bins. Where there aren't any these should be provided.

| Park: | Roman Way Park |
|------------------|--------------------------------|
| Address: | Roman Way, Folkestone CT19 4JU |
| Proposed budget: | £50,000 |

Photo





Context

Roman Way Park is a large green space close to a large residential area housing many families. It has a range of play equipment in a dedicated play area and has a large green open space with goalposts and basketball hoop. It is accessed from the south and east sides and shares the space with some council owned garages to the west of the site. The northern edge borders a busy road servicing a large supermarket and business park.

This is a busy and popular park for children and families of all ages. There is an opportunity for this to be a real showpiece park for the people living nearby.

Мар



| Equipment | | Condition |
|-----------|--------------------------------|-----------|
| | Basketball net with goal posts | Good |
| | Slide and climbing frame | Good |
| | Swings | Replace |

Contractors are encouraged to suggest replacement play equipment that is robust, has proven benefits to users and will enhance the play experience in this park. Attention should be given to the public feedback about this park given later in this report. Contractors are encouraged to think more widely about the space and whether the dedicated play area is in the best place. Could there be provision for ball games for older children? Can a natural separation be made between the park and the road? Is there space for something as exciting as a zip wire?

Contractors are encouraged to suggest replacement floor surfaces that are robust, attractive and will enhance the visitor experience in this park. There is some missing fence, and some fences could be moved or reused. Consideration should be given to whether additional fence would be beneficial.

This is large park with very little else in close proximity. It would benefit from maximising the space available to include as much acidity as possible including sport. The park is used by children of all ages. This park could benefit from a total revamp and consideration given to the overall design. The council would like to make this a showpiece park.

| How do you use the Park? | |
|--|---------------------|
| Walking | 10.00% |
| Childrens Play | 80.00% |
| other | 10.00% |
| What facilities would you like to see developed or improved at Coniston Road Park? | |
| Swings | <mark>88.89%</mark> |
| Slide | <mark>88.89%</mark> |
| Climb | <mark>88.89%</mark> |
| Toddler Play | 66.67% |
| Adventure Play | 77.78% |
| Sensory/inclusive | 33.33% |
| Sports/ Active | 77.78% |
| Picnic/seating | 77.78% |
| other | 11.11% |

Contractors are encouraged to suggest furniture that is robust, attractive and will enhance the visitor experience in this park. Consideration should be given to provision of litter and poo bins. Where there aren't any these should be provided.

Park: Southern Way

Address: Southern Way, Folkestone CT20 1HV

Proposed budget: £40,000

Photo





Context

Southern Way Park is an open space with a range of play equipment and open space covered with grass. It is bordered on the South side by residential properties on Folly Road and Morrison Road. On the North side is the A260 a busy road on a main bus route. There are two primary schools nearby and the park is on the way home for many families.

Мар



| Current Equipment | Condition |
|---|-----------|
| Swings | Remove |
| Seesaw | Remove |
| Slide | Remove |
| Roundabout in storage with base in situ | Reinstall |
| Picnic benches | Remove |
| Agility tunnel | Repair |
| Rope spinner | Repair |

Contractors are encouraged to suggest replacement play equipment that is robust, has proven benefits to users and will enhance the play experience in this park. Attention should be given to the public feedback about this park given later in this report. This park experiences Anti-Social Behaviour. Floor surfaces and play equipment have damaged and removed in the past. Graphic graffiti has had to be removed. Consideration should be given to the robustness of any equipment or furniture used in this park.



| ve shrunk |
|-------------|
| around |
| |
| ooling of |
| n strategic |
| |
| ng parts. |
| e. |
| |

Contractors are encouraged to suggest replacement floor surfaces that are robust, attractive and will enhance the visitor experience in this park.

| Desires | | | | | |
|-----------|---|--|--|--|--|
| | A nice picnic area and /or gathering spaces. Better play | | | | |
| | equipment and new play equipment where current | | | | |
| | equipment is beyond repair. | | | | |
| | Can a creative solution be found for enhanced play in the | | | | |
| | open grass area that doesn't impinge on Southern Water | | | | |
| | access to the site? | | | | |
| Age range | | | | | |
| | Up to 11 (Primary school age) | | | | |
| Notes | | | | | |
| | The site is owned by Southern Water and leased to FTC on a | | | | |
| | long lease. Access must be maintained for SW to an access | | | | |
| | hatch in the centre of the grass area. Nothing can be built | | | | |
| | over this area. | | | | |
| | | | | | |

Contractors are encouraged to suggest furniture that is robust, attractive and will enhance the visitor experience in this park. Consideration should be given to provision of litter and poo bins. Where there aren't any these should be provided.



Public feedback

| Fublic lecuback | |
|--------------------------|--------|
| How do you use the Park? | |
| Walking | 10.00% |
| Childrens Play | 90.00% |

| What facilities would you like to see developed or improved at Southern Way Park? | |
|---|---------|
| Swings | 80.00% |
| Slide Slide | 80.00% |
| Climb | 80.00% |
| Toddler Play | 40.00% |
| Adventure Play | 100.00% |
| Sensory/inclusive | 30.00% |
| Sports/ Active | 10.00% |
| Landscaping | 20.00% |
| Picnic/seating | 80.00% |