



Red hatched area highlights the location of the early years soft play to be re-surfaced and all play equipment to be reinstated.

Blue hatched area highlights the location of the soft play tarmac in the main school playground to be re-surfaced and all play equipment to be reinstated.

Notes:
The contractor must verify all dimensions on site before commencing any work on shop drawings, do not scale from this drawing
McBains Ltd copyright

BIM Transmittal Disclaimer
McBains Ltd makes no express or implied warranties with respect to the character, function, or capabilities of the data (inclusive of 3rd party data incorporated within), or the suitability of the data for any particular purpose beyond those originally intended by McBains Ltd. Please refer to our standard terms and conditions for further details.

Revision	Amendment		Date
ME	LM	LM	
Drawn by	Reviewed by	Approved by	
61984B	JAN-23	1:250 @ A1	
MCB Number	Date created	Scale	

McBains Ltd
5th Fl, 26 Finsbury Square London EC2A 1DS
+44 (0)20 7786 7900
mcbains.co.uk

Client:
LONDON BOROUGH OF MERTON

Project
RESURFACING PACKAGE
HATFIELD PRIMARY SCHOOL
LOWER MORDEN LANE, SM4 4JS

Drawing Title
INDICATIVE LOCATION OF THE SOFT PLAY AREA TO BE RE-SURFACED
HATFIELD PRIMARY SCHOOL

BUILDING SURVEYING

Drawing / Document Reference							Status								
MER01	·	MCB	·	XX	·	ZZ	·	DR	·	B	·	0201	S3	·	P1
Project Idem	Originator	Zone	Level	Type	Discipline	Number	Suitability Revision								