

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Basement
Location ID	2F D8 15 F3	Room / Area	Auditorium
Building	Museum	Description	No suspect materials observed within area / room

**MANAGEMENT SUMMARY**

Action		Material Assessment		Combined Risk Score	
		Priority Assessment			
Comments:	Modern stair nosing (White)				
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	29/05/2009	Lab Reference	
Next Inspection Date		Sample Reference	Visual Inspection
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Presumed

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Basement
Location ID	3B E3 20 98	Room / Area	Electrical Cupboard
Building	Museum	Description	Presume asbestos containing materials within 'MEM' switch boxes



MANAGEMENT SUMMARY

Action		Material Assessment Priority Assessment	9	Combined Risk Score	
Comments:	2007 Recommendations have not been carried out				
Recommendations:	Please apply caution				

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	06/10/2011	Lab Reference	
Next Inspection Date	05/10/2012	Sample Reference	Presume
Survey Type	Reinspection	Asbestos Identification	Presumed

MATERIAL ASSESSMENT (SCORE = 9)

Product Type	3	3	Surface Treatment	3	3
Extent of Damage / Deterioration	Good condition: No visible damage	0	Asbestos Type	3	3

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/ Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Present

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Basement
Location ID	8E C2 46 6E	Room / Area	Electrical Cupboard
Building	Museum	Description	Asbestos insulating board (AIB) panels to ceiling and slope of underside of stairs

**MANAGEMENT SUMMARY**

Action		Material Assessment	5	Combined Risk Score	
Comments:	2007 Recommendations have been carried out				
Recommendations:	Continue to manage via periodic review				

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	06/10/2011	Lab Reference	
Next Inspection Date	05/10/2012	Sample Number	E290/03
Survey Type	Reinspection	Asbestos Identification	Present

MATERIAL ASSESSMENT (SCORE = 5)

Product Type	2	2	Surface Treatment	1	1
Extent of Damage / Deterioration	Good condition: No visible damage	0	Asbestos Type	2	2

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Basement
Location ID	F7 7E 31 9A	Room / Area	Ladies WC
Building	Museum	Description	No suspect materials observed within area / room

**MANAGEMENT SUMMARY**

Action		Material Assessment		Combined Risk Score	
		Priority Assessment			
Comments:					
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	29/05/2009	Lab Reference	
Next Inspection Date		Sample Reference	Visual Inspection
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Basement
Location ID	29 9D BE 34	Room / Area	Lockers & Storage
Building	Museum	Description	No suspect materials observed within area / room

**MANAGEMENT SUMMARY**

Action		Material Assessment Priority Assessment		Combined Risk Score	
Comments:					
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	29/05/2009	Lab Reference	
Next Inspection Date		Sample Reference	Visual Inspection
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Basement
Location ID	1F A6 52 29	Room / Area	Lower Gallery Area 1
Building	Museum	Description	No suspect materials observed within area / room

**MANAGEMENT SUMMARY**

Action		Material Assessment Priority Assessment		Combined Risk Score	
Comments:	Area is made up from plasterboard and timber scenery MMM pipe lagging where inspected				
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	29/05/2009	Lab Reference	
Next Inspection Date		Sample Reference	Visual Inspection
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Basement
Location ID	76 A0 1D 66	Room / Area	Lower Gallery Area 2
Building	Museum	Description	No suspect materials observed within area / room

**MANAGEMENT SUMMARY**

Action		Material Assessment Priority Assessment		Combined Risk Score	
Comments:	Area is made up from plasterboard and timber scenery MMMF pipe lagging where inspected				
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	29/05/2009	Lab Reference	
Next Inspection Date		Sample Reference	Visual Inspection
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/ Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Basement
Location ID	3E D9 08 A2	Room / Area	Lower Gallery Area 3
Building	Museum	Description	No suspect materials observed within area / room

**MANAGEMENT SUMMARY**

Action		Material Assessment Priority Assessment		Combined Risk Score	
Comments:	Area is made up from plasterboard and timber scenery MMMF pipe lagging where inspected				
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	29/05/2009	Lab Reference	
Next Inspection Date		Sample Reference	Visual Inspection
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Basement
Location ID	88 49 F7 6C	Room / Area	Male WC
Building	Museum	Description	No suspect materials observed within area / room

**MANAGEMENT SUMMARY**

Action		Material Assessment		Combined Risk Score	
		Priority Assessment			
Comments:					
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	29/05/2009	Lab Reference	
Next Inspection Date		Sample Reference	Visual Inspection
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Basement
Location ID	30 5A 86 0B	Room / Area	Staff Room
Building	Museum	Description	Damper pad to base of sink

**MANAGEMENT SUMMARY**

Action		Material Assessment		Combined Risk Score	
		Priority Assessment			
Comments:					
Recommendations:	No asbestos detected in sample. No further action is required				

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	29/05/2009	Lab Reference	
Next Inspection Date		Sample Number	E290/04
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Basement
Location ID	F8 BE CD 08	Room / Area	Stairs & Corridor
Building	Museum	Description	No suspect materials observed within area / room

**MANAGEMENT SUMMARY**

Action		Material Assessment		Combined Risk Score	
		Priority Assessment			
Comments:	Modern stair nosing (Black)				
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	29/05/2009	Lab Reference	
Next Inspection Date		Sample Reference	Visual Inspection
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Basement
Location ID	C7 A2 0D C6	Room / Area	Stairs Lobby Area
Building	Museum	Description	Area Accessed - No Asbestos Found

**MANAGEMENT SUMMARY**

Action		Material Assessment		Combined Risk Score	
		Priority Assessment			
Comments:					
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	06/10/2011	Lab Reference	
Next Inspection Date		Sample Number	
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment	
Extent of Damage / Deterioration		Asbestos Type	

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Basement
Location ID	D2 B0 B2 52	Room / Area	Store Room
Building	Museum	Description	No suspect materials observed within area / room

**MANAGEMENT SUMMARY**

Action		Material Assessment		Combined Risk Score	
Comments:					
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	29/05/2009	Lab Reference	
Next Inspection Date		Sample Reference	Visual Inspection
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Basement
Location ID	02 3D 58 31	Room / Area	Toilet Corridor
Building	Museum	Description	No suspect materials observed within area / room

**MANAGEMENT SUMMARY**

Action		Material Assessment		Combined Risk Score	
Comments:					
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	29/05/2009	Lab Reference	
Next Inspection Date		Sample Reference	Visual Inspection
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Basement
Location ID	DA 31 94 88	Room / Area	Work Room Store
Building	Museum	Description	No suspect materials observed within area / room

**MANAGEMENT SUMMARY**

Action		Material Assessment Priority Assessment		Combined Risk Score	
Comments:	Plasterboard rear wall behind racking				
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	29/05/2009	Lab Reference	
Next Inspection Date		Sample Reference	Visual Inspection
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/ Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Removed

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Basement / Ground
Location ID	00 83 3E D8	Room / Area	Stairs to Ground Floor
Building	Museum	Description	Asbestos bonded stair nosing (Black)

**MANAGEMENT SUMMARY**

Action		Material Assessment		Combined Risk Score	
		Priority Assessment			
Comments:	material removed in 2010				
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	06/10/2011	Lab Reference	
Next Inspection Date		Sample Number	
Survey Type	Reinspection	Asbestos Identification	Removed

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Ground / Basement
Location ID	9A 06 10 A8	Room / Area	Stairs & Lobby
Building	Museum	Description	No suspect materials observed within area / room

**MANAGEMENT SUMMARY**

Action		Material Assessment		Combined Risk Score	
		Priority Assessment			
Comments:	Modern stair nosing				
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	29/05/2009	Lab Reference	
Next Inspection Date		Sample Reference	Visual Inspection
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Presumed

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Ground / Basement
Location ID	96 8D 4E FA	Room / Area	understairs cupboard adjacent to the courtyard
Building	Museum	Description	Remaining intact ceiling and soffit is assumed to be similar material (amosite)

MANAGEMENT SUMMARY

Action		Material Assessment	11	Combined Risk Score	
Comments:	Note: the previously unidentified disturbed soffit in the understairs cupboard adjacent to the courtyard has been found to contain Amosite, the remaining intact ceiling and soffit is assumed to be a similar material and requires managing.				
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	06/10/2011	Lab Reference	
Next Inspection Date	05/10/2012	Sample Reference	Presume
Survey Type	Reinspection	Asbestos Identification	Presumed

MATERIAL ASSESSMENT (SCORE = 11)

Product Type	3	<u>3</u>	Surface Treatment	3	<u>3</u>
Extent of Damage / Deterioration	3	<u>3</u>	Asbestos Type	Amosite (brown)	<u>2</u>

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Removed

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Ground / Basement
Location ID	C0 21 EF DA	Room / Area	understairs cupboard adjacent to the courtyard
Building	Museum	Description	Soffit - Understairs cupboard - Containing Amosite

MANAGEMENT SUMMARY

Action		Material Assessment		Combined Risk Score	
		Priority Assessment			
Comments:					
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	06/10/2011	Lab Reference	
Next Inspection Date		Sample Number	
Survey Type	Reinspection	Asbestos Identification	Removed

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Ground Floor
Location ID	D4 BB 62 3B	Room / Area	All Rooms
Building	Museum	Description	No Asbestos Detected

**MANAGEMENT SUMMARY**

Action		Material Assessment Priority Assessment		Combined Risk Score	
Comments:					
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	06/10/2011	Lab Reference	
Next Inspection Date		Sample Number	
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Ground Floor
Location ID	28 65 BD C8	Room / Area	Education Lecture Room
Building	Museum	Description	Damper pad to base of sink

**MANAGEMENT SUMMARY**

Action		Material Assessment Priority Assessment		Combined Risk Score	
Comments:					
Recommendations:	No asbestos detected in sample. No further action is required				

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	29/05/2009	Lab Reference	
Next Inspection Date		Sample Number	E290/01
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Presumed

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Ground Floor
Location ID	FD C4 3B E8	Room / Area	Education Lecture Room
Building	Museum	Description	Presume asbestos containing materials within wall mounted heater unit



MANAGEMENT SUMMARY

Action		Material Assessment	9	Combined Risk Score	
Comments:	No access to inspect. Live or in use at time of survey Treat all other heaters as uniform composition 2007 Recommendations have not been carried out				
Recommendations:	Please apply caution				

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	06/10/2011	Lab Reference	
Next Inspection Date	05/10/2012	Sample Reference	Presume
Survey Type	Reinspection	Asbestos Identification	Presumed

MATERIAL ASSESSMENT (SCORE = 9)

Product Type	3	<u>3</u>	Surface Treatment	3	<u>3</u>
Extent of Damage / Deterioration	Good condition: No visible damage	<u>0</u>	Asbestos Type	3	<u>3</u>

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/ Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Ground Floor
Location ID	E5 E5 67 D9	Room / Area	Exhibition Gallery 1
Building	Museum	Description	No suspect materials observed within area / room including cupboards

**MANAGEMENT SUMMARY**

Action		Material Assessment		Combined Risk Score	
		Priority Assessment			
Comments:	The area is made up from timber and plasterboard				
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	29/05/2009	Lab Reference	
Next Inspection Date		Sample Reference	Visual Inspection
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Ground Floor
Location ID	2C 15 AF 75	Room / Area	Exhibition Gallery 2
Building	Museum	Description	No suspect materials observed within area / room

**MANAGEMENT SUMMARY**

Action		Material Assessment Priority Assessment		Combined Risk Score	
Comments:	The area is made up from timber and plasterboard scenery rooms				
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	29/05/2009	Lab Reference	
Next Inspection Date		Sample Reference	Visual Inspection
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Present

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Ground Floor
Location ID	5E F2 D1 25	Room / Area	Exhibition Gallery 3
Building	Museum	Description	Asbestos bonded step nosing to perimeter of raised plinth (Black) Modern thermoplastic tiles (Grey) and hardboard below carpet throughout area

**MANAGEMENT SUMMARY**

Action		Material Assessment	2	Combined Risk Score	
Comments:	2007 Recommendations have been carried out				
Recommendations:	Continue to manage via periodic review				

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)		
Last Inspection Date	06/10/2011	Lab Reference			
Next Inspection Date	05/10/2012	Sample Number	E290/02		
Survey Type	Reinspection	Asbestos Identification	Present		

MATERIAL ASSESSMENT (SCORE = 2)

Product Type	1	<u>1</u>	Surface Treatment	0	<u>0</u>
Extent of Damage / Deterioration	Good condition: No visible damage	<u>0</u>	Asbestos Type	1	<u>1</u>

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Ground Floor
Location ID	B0 C3 54 E0	Room / Area	External Elevations
Building	Museum	Description	No suspect materials observed within area up to 2.5m

**MANAGEMENT SUMMARY**

Action		Material Assessment		Combined Risk Score	
Comments:					
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	29/05/2009	Lab Reference	
Next Inspection Date		Sample Reference	Visual Inspection
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment	
Extent of Damage / Deterioration		Asbestos Type	

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Ground Floor
Location ID	15 31 C5 75	Room / Area	Main Entrance & Foyer
Building	Museum	Description	No suspect materials observed below ceiling

**MANAGEMENT SUMMARY**

Action		Material Assessment		Combined Risk Score	
Comments:	Part of the ceiling is timber clad				
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	29/05/2009	Lab Reference	
Next Inspection Date		Sample Reference	Visual Inspection
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Ground Floor
Location ID	88 C1 69 C3	Room / Area	Museum Office
Building	Museum	Description	No suspect materials observed within area / room

**MANAGEMENT SUMMARY**

Action		Material Assessment Priority Assessment		Combined Risk Score	
Comments:					
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	29/05/2009	Lab Reference	
Next Inspection Date		Sample Reference	Visual Inspection
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	

ASBESTOS - Not suspected

Address	Museum of Oxford, St Aldate's, Oxford, OX1 1DZ		
Site ID	200001115548	Floor	Ground Floor
Location ID	C4 0D D6 A7	Room / Area	Museum Shop
Building	Museum	Description	No suspect materials observed below ceiling

**MANAGEMENT SUMMARY**

Action		Material Assessment		Combined Risk Score	
		Priority Assessment			
Comments:	Display racking to all walls				
Recommendations:					

SURVEY INFORMATION

Surveyed	YES	Source of Information	T Lewis (CWE Services Limited)
Last Inspection Date	29/05/2009	Lab Reference	
Next Inspection Date		Sample Reference	Visual Inspection
Survey Type	Reinspection	Asbestos Identification	Not suspected

MATERIAL ASSESSMENT

Product Type		Surface Treatment		
Extent of Damage / Deterioration		Asbestos Type		

MANAGEMENT ASSESSMENT

Normal Occupancy/ Activity		Human Exposure Potential/Number of Occupants	
Secondary Activities in Area		Frequency of Use	
Location		Average Time in Use	
Accessibility		Maintenance Activity	
Amount		Maintenance Frequency	