

1.



1. View of Walton Street at the roundabout with Exchange Street to the right

2.



2. Closer view with BCC building to the left. Lamp-post here is different from the others on this section of Walton Street

3.



3. View from the path of 'lower' Walton Street. In the distance you can see the smaller decorative black lamp-posts. BCC to the left, with Miya Japanese restaurant on the left corner and the side view to the left of The Courtyard Gin Bar. Buses use a mix of this route or from the bus Station turning left which brings you the long way around to this roundabout.

4.



4. Wider shot to incorporate the side view of BCC with trees obscuring the side



5.



5. on the path by Miya Japanese restaurant. Note that the paving slabs change here to block paving and slope left towards the road

6.



6.

Path by Miya reverts back to larger slabs, but are uneven. Utilities access box to the right and on left-side front of BCC. By lamppost in the path is a Utilities access point



7.



7. Lamp-post has seen better days! Looking up the Street you can see the more ornate lamp-posts, outside Old County Hall. The paving here is a mix of old and replaced slabs, some cracked and of various colouration.

8.



8. Further view up the road showing further slab replacement and another Utilities access point on the floor



9.



9. First of decorative lamp-posts – this is degraded with paint peeling off. On the floor by the lamp-post is a further Utilities access, with another at the exit point of the car access outside Old County Hall.

The one-way sign is bent and here grass is growing through gaps in pavement

10.



10. Old County Hall is to the right. Here in the path curb dropped and paved access point to cross the road. To the right of the picture is the Porters Lodge building, owned by BCC



11.



11. Showing grass growing in space around lamp-post. Path is more even here and less replacement slabs

12.



12. To the right is the railings of Old County Hall. These require re-painting. The barrier is for access to the car spaces in front of Old County Hall and the side of 5-7 Walton Street, showing signs of wear on the wall. Going through barrier you pass a walkway that connects Judges Lodgings on the left and the new Waterside North carpark to the right



13.



13. Wider shot to show Aylesbury lending Library and above is the Friars square Shopping Centre

14.



14. Looking towards the walkway between Old County Hall and 5-7 Walton Street directly to left of frame. Next to that is the Training Suite also owned by BCC. At the end of the walkway you can just see the steps up to the side of Judges Lodgings. From these steps left is the Judges Lodges car park and complex, which leads out on to the new complex, 'The Exchange' and to right of the steps brings you to the back of Old County Hall and Waterside North carpark



15.



**15.** View straight on to the walkway. Brink plinth use to have a large urn on. Asphalt area with utilities access, moving into slabs. To right of the stairs is mobility access

16.



**16.** From the side of 5-7 Walton Street, looking towards the top of Walton Street.

In the foreground another Utilities access box and on the path a drain cover and in the centre of the path towards the vehicle is another utilities access point. By the box is a new placed parking meter.



17.



17. Wider angle of the top of Walton Street. To the right is the Swan PH and next to that is The Bell PH. At the top of the frame is flats and a gym to the left. If you turn right you come to the bottom of the Market Square and the road left is Station Way. At the top left is @The Hub', for all travel information and building to the left is the elevated section of Friars Square Shopping Centre.

18.



18. Closer image of the pathway detailing utilities access. Again grass and weeds growing through path and gaps from buildings and path



19.



19. Closer view of side entrance to The Bell PH. Pathway here is a mix of asphalt and concrete, the asphalt being in a poor state of repair

20.



20. Top end of Walton Street looking towards Station Way which is a road going under the Shopping Centre, the left of which houses the Bus Station. The glass and steel structure is 'The Hub' Travel Information centre and there are some steel bike park frames.



21.



21. Wider shot of the top end with Station Way and Travel Information Centre.

22.



22. Different angle, showing further utilities access in the road



23.



23. Looking down from the top of Walton Street. In this frame you can see the decorative lamp-posts

24.



24. With Travel Information centre to right of the frame. View of entrance to lending library and view from side of the library. Note the old sign for Walton Street on the wall.



**25.**



**26.**



**27.**



**25. 26. & 27.**

Showing different views of the same section. Note area is suffering from grass/weeds growing through block paving and outlet in concrete wall has algae on the wall. Side access to library or some kind of utility area. Railings need re-painting and boarding is discoloured see frame 26.

Travel Information Centre is frame 26 shows empty revolving leaflet holders a reminder that is it being utilised?



**28.**



**28.** View down top end of Walton Street from other side of the road. Path is in better state of repair on this side, but along this side is numerous cigarette ends and rubbish potentially from the Market and Town. Again in the frame you can see various utility access points. Parking in the bays to left of frame are for disability badge holders

**29.**



**29.** Closer view of path and utility access points



**30.**



**30.** View showing the restricted bay in red block paving. There is a green 'strip' running down this side of the road for cyclists. This runs in the opposite direction to the one-way traffic. Across the road is the new parking area, which narrows the road width.

**31.**



**31.** Bike parking racks have been added and do appear to be used. In this frame you can see the unsightly underside of the over-hang from Friars square shopping Centre.



**32.**



**32.** Frame showing closer shot of the bike racking and the one bin on the street. To the right is BCC.

**33.**



**33. & 34.** Side of BCC building and to the right is an open alleyway that splits into two. The nearest by the salt grip unit takes you up two flights of unsightly stairs to go left to BCC (employees only) or right into Friars Square shopping. The other path takes you between BCC and the Bus Station (no access this way) and onto the A41. To note further utilities access and deteriorated railing. To left the green railings contain BCC's bike store and directly left is BCC's mobility access ramp system. There is a void under the stairs and this used occasional by homeless seeking shelter or the strong waft of drugs as is a good hideaway

**34.**





**35.**



**35.** Coming to the right-side of the front of BCC. Algae and moss can be seen on the ledge. Close up of seating put in that is not being utilised, other than for BCC employees and visitors that smoke

**36.**



**36.** This is a frame of the left-hand side of BCC. Again algae and moss and water staining can be seen. More seating here, this being the side most used by smokers. Path on this section is mix of different coloured paving slabs and block paving



**37.**



**37.** Front of BCC, with signage that will presumably be changed with Unitary. The tree is the only one in the road and looks slightly out of place.

**38.**



**38.** Planter in broken drain cover. In the distance further utility access points. Here you can see the varying paving slabs used and benches which have algae growing on the path under them.



**39.**



**40.**



**39. & 40.** Closer view of benches, some are broken, an example in frame 40. The ground has scattered cigarette butts and in frame 40 is a cigarette packet



41.



42.



**41 & 42.** Side-view of BCC. In frame 42 the metal plate may be the remnant of a cigarette extinguisher, therefore at present there is nowhere to extinguish and dispose of cigarettes other than the bin at the top of the stairs. Here you can also see the algae on the steps that are exposed to the elements.



**43.**



**43.** Close up of the stairs leading to BCC entrance

**44.**



**44.** This is the view from the roundabout looking up Walton Street. Further utility access points can be seen in the path. Here you can clearly see the cycle lane with markings to show you can only go up the street, when all other traffic is one way, coming down the street. The grass area is adjacent to entrance to the Bucks Learning centre



**45.**



**45.** This further towards the roundabout with a wider shot of the grass area which has trees and bushes, that proceeds around the corner to the A413. There is a pathway to the left of the frame that leads into the area and to the Bucks Learning Centre

**46.**



**46.** View of the path



**47.**



**47.** Closer view of 'green' area. Grass is patchy and whole area looking in need of some attention

**48.**



**48.** View from roundabout looking at the other side of Walton Street and Miya Japanese restaurant