

## \*GSH Site Survey Doc

3364 / GSH Site Survey	Complete
Document title:	GSH Site Survey
GSH project number (if applicable):	3364
GSH representative(s) present during survey:	Darren Doughty
Date:	07.11.2023 14:18 GMT
Client/Site Details:	
Client name:	Other
Client name:	North Somerset Council
Contact:	Jasmin Williams
If location services are unavailable, please manually input or correct the address	
Site Address:	Cove kiosk Weston super mare beach BS23 1AL

## **Survey of Works:**

Click to add Works Details and Photos for Each Location:

Click to add Works Details and Photos for Each Location: 1

## Photos:













Photo 5



Photo 6



Photo 7





Photo 14



Photo 9

Photo 15





Photo 11



Photo 12

Photo location and works description:

Cove kiosk **Site Survey** 1 Flooring internal old floor tiles possibly containing asbestos needs ceiling and replacing 2 walls and ceiling seem solid and white hygiene board **3 electrical needs checking** 4 felt roof looks worn and torn needs replacement advise fibreglass roof 5 Decking in places rotten and sunken down possibly unsafe Needs replacement sub structure needs investigation 6 exterior cladding to building seems solid Measurements (ie m2/Linear Lengths/Ceiling Heights etc): On CAD Additional Notes/comments (ie Any obvious H&S issues/Access N/a Issues etc): Plant required (Internal Access Tower/Long Ladders/Barriers N/a etc): GSH Contractor to carry out works: **Declarations:** 

GSH signature:



Darren Doughty 07.11.2023 14:20 GMT

## Media summary



Photo 1



Photo 3



Photo 5



Photo 2



Photo 4



Photo 6



Photo 7




Photo 9




Photo 8



Photo 10




Photo 11




Photo 13




Photo 12



Photo 14

