APPENDIX 6

	Felling of Roadside and Greenway Ash impacted by Ash Die Back Disease 2022
Lot Number	6
Date	29/4/2022
Site Address	A367 Odd Down to Dunkerton Bottom, BA2 8BU
Summary Job Description	Fell All Ash stems marked in orange paint growing in Highway Verges approximate locations shown on plans. Total no. Approximately 171
Site Specific Information	Traffic Management is essential with details of traffic management proposed and evidence of approval of TM from Council's Street Works Team to be included in tender documents. Streetworks Team can be contacted by email Street_Works@BATHNES.GOV.UK

Ash Dieback Felling plan A367 Odd Down Park and Ride to Dunkerton Bottom

Trees to fell marked in red with red label indicating number of stems to fell. Number of stems corresponds with number of stems marked with orange spray. Group trees not individually marked.

Section1; Park and ride to Fullers Earth

Section 2 Green lane to Crossways

Section 3 Crossways to layby

Section 4, layby to village. G1; small stems, approx. 70 stems. Orange marks on kerb. G2 saplings