



Photo 1: TP01 prior to excavation.



Photo 2: TP01 track bed





Photo 3: Bridge deck slab revealed within TP01



Photo 4 TP01 arisings



Photo 4: TP02 prior to excavation





Photo 5: Track bed revealed within TP02



Photo 6: Bridge deck slab revealed within TP02



Photo 7: TP03 prior to excavation.



Photo 8: Groundwater within TP03





Photo 9: TP03 arisings.



Photo 10: Track bed revealed within TP04



Photo 11: TP04 arisings



Photo 12: Track bed revealed within TP05





Photo13: Groundwater revealed within TP05



Photo 14: TP05 arisings





Photo 15: TP06 after excavation



Photo 16: Track bed revealed within TP06





Photo 17: Arisings from TP06



Photo 18: Track bed revealed within TP07





Photo19: Arisings from TP07



Photo 20: Track bed revealed within WS08





Photo 21: TP08 arisings



Photo 22: Track bed revealed within TP09





Photo 23: Alternate view of track bed and ground profile within TP09



Photo 24: Groundwater seepage within TP09





Photo 25: TP09 arisings




Photo 26: Track bed revealed within TP10





Photo 27: TP10 arisings



Photo 28: View of the track bed revealed within TP11





Photo 29: Groundwater seepage within TP11



Photo 30: TP11 arisings



Photo 31: View of the track bed within TP12



Photo 32: General view of TP12





Photo33: Limestone boulder excavated from TP12



Photo 34: View of the arisings from TP12





Photo 35: View of the track bed material within TP13.



Photo 36: View of the arisings from TP13





Photo 37: View of the track bed within TP14



Photo 38: View of the track bed and made ground within TP14





Photo 39: View of the arisings from TP14



Photo 40: View of the track bed within TP15





Photo 41: Groundwater seepage within TP15



Photo 42: View of the arisings from TP15