










**NOTES**  
JOB No.: 1534  
SURVEY DATE: 28/09/2018 & 16/10/2018  
SURVEYED: AG  
DISUSED SERVICES NOT SURVEYED.  
INTERNAL AREAS NOT SURVEYED.

**DISCLAIMER**  
GROUNDSCAN LTD. AND ITS EMPLOYEES SHALL NOT BE RESPONSIBLE FOR ANY DAMAGE TO PERSONS OR PROPERTY ARISING FROM THE USE OF THE INFORMATION CONTAINED HEREIN. THE INFORMATION IS PROVIDED AS IS, WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED, INCLUDING BUT NOT LIMITED TO THE WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT. IN NO EVENT SHALL GROUNDSCAN LTD. BE LIABLE FOR ANY SPECIAL, INCIDENTAL OR CONSEQUENTIAL DAMAGES ARISING FROM THE USE OF THE INFORMATION CONTAINED HEREIN.

| PAS 128: 2014      |               |                                                                                                                                                |
|--------------------|---------------|------------------------------------------------------------------------------------------------------------------------------------------------|
| SURVEY CATEGORY    | QUALITY LEVEL | CRITERIA USED IN THE DETERMINATION OF QUALITY LEVEL                                                                                            |
| TYPE B - DETECTION | QL B1         | QUALITY LEVEL B1: ALL SERVICES DETECTED AND LOCATED TO A DEPTH OF 1.0M.                                                                        |
|                    | QL B2         | QUALITY LEVEL B2: ALL SERVICES DETECTED AND LOCATED TO A DEPTH OF 1.0M, WITH A CONFIDENCE IN DEPTH OF 0.5M.                                    |
|                    | QL B3         | QUALITY LEVEL B3: ALL SERVICES DETECTED AND LOCATED TO A DEPTH OF 1.0M, WITH A CONFIDENCE IN DEPTH OF 0.5M, AND A CONFIDENCE IN DEPTH OF 0.5M. |
|                    | QL B4         | QUALITY LEVEL B4: ALL SERVICES DETECTED AND LOCATED TO A DEPTH OF 1.0M, WITH A CONFIDENCE IN DEPTH OF 0.5M, AND A CONFIDENCE IN DEPTH OF 0.5M. |



| ABBREVIATIONS             |                        |
|---------------------------|------------------------|
| AR ASSUMED ROUTE          | PE POLYETHYLENE        |
| BD BACKDROP               | PR PIPE RISER          |
| BL BLOTTED                | PVC POLYVINYL CHLORIDE |
| BTC BT INSPECTION CHAMBER | RE RODDING EYE         |
| CI CAST IRON              | RWP RAIN WATER PIPE    |
| CL COVER LEVEL            | ST STOP TAP            |
| CP CABLE PIT              | SV STOP VALVE          |
| CR CABLE RISER            | SVP SOIL VENT PIPE     |
| EM EARTH MAT              | TFR TAKEN FROM RECORDS |
| EP ELECTRICITY POLE       | TL TELEGRAPH POLE      |
| EOT END OF TRACE          | UTL UNABLE TO LOCATE   |
| FE FENCE EARTH POINT      | UTR UNABLE TO RAISE    |
| FH FIRE HYDRANT           | UTS UNABLE TO SURVEY   |
| GV GAS VALVE              | UTT UNABLE TO TRACE    |
| GY GULLY                  | VP VENT PIPE           |
| IC INSPECTION CHAMBER     | VR VAPOUR RECOVERY     |
| IL INVERT LEVEL           | WL WATER LEVEL         |
| LP LAMP POST              | WM WATER METER         |
| MH MANHOLE                | WO WASTEWATER VALVE    |
| NPT NO PRES. RISER        | WMP WASTE WATER PIPE   |
| OSA OUTSIDE SURVEY AREA   |                        |

| LEGEND |                            |
|--------|----------------------------|
|        | BOREHOLE (BH)              |
|        | BOREHOLE PROPOSED LOCATION |
|        | BT                         |
|        | CABLE TV CATV              |
|        | CLOSED CIRCUIT TV          |
|        | COMMS                      |
|        | EMPTY DUCT                 |
|        | FIBRE OPTICS               |
|        | GAUGE LINES                |
|        | TRAFFIC SIGNALS            |
|        | ELECTRIC HV                |
|        | ELECTRIC                   |
|        | FUEL LINES                 |
|        | OFFSET FILL                |
|        | VENT                       |
|        | FUEL PIPE                  |
|        | GAS                        |
|        | WATER                      |
|        | OIL                        |
|        | COMPRESSED AIR             |
|        | RADAR TRACE                |
|        | UNKNOWN TRACE              |
|        | DRAINAGE FOUL              |
|        | DRAINAGE SURFACE           |
|        | OUTFALL                    |
|        | RISE MAIN                  |
|        | END OF TRACE               |
|        | SURVEYED AREA              |

**groundscan**  
Unit 4, The Old Glove Factory,  
Bristol Road,  
Sherborne,  
Dorset DT9 4HP  
Tel: 01935 389123  
Website: www.groundscan.co.uk  
Company Reg: 07847795

|                                            |                           |
|--------------------------------------------|---------------------------|
| Client: PIPEFIX                            |                           |
| Survey Location: POOLE PARK, POOLE, DORSET |                           |
| Survey type: UTILITY                       | Scale: 1:250<br>Sheet: A0 |
| Drawing ref: G18539 SHEET 2 OF 2           | Date: 17/10/2018          |
| Drawn/DA: AG                               | Issue: 2                  |