


Appendix 4 - Examples of recently completed marine engineering works in Torbay



Hollicombe Rock Armour cliff protection May 2017



Princess Pier toe encasement Feb 2016





Harbour structures surveys April 2015




Pontoon and access brow, Brixham 2013





Brixham Breakwater survey November 2017



Brixham Inner harbour drying grid April 2016





Emergency sprayed concrete works to sea wall, Meadfoot May 2016

Works pre 2013



Reinforced sprayed concrete protection to seaward face of Haldon Pier, Torquay




Bagwork and mass concrete repair of scour damage/voids to foundation of Haldon Pier, Torquay



Repair by pressure pointing/grouting of section of bellying masonry, Crane Pier, Brixham






Repair of timber fenders, Crane Pier, Brixham Harbour, Brixham



RC construction to Princess Promenade, Torquay



Passive CP installation and repair, Brixham Harbour, Brixham



Installation of gangway, Haldon Pier, Torquay